

TOWNSHIP 30 RANGE 09 POINT IDENTIFIER # 700200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 25 & 36; 30 & 31, T30-8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol 17 Pgs 7371-72)

-----  
Set post, cor. secs. 25, 36, 30 and 31, from which  
A Fir 15" dia., bears N.47°W., 37 lks. dist.  
A Fir 30" dia., bears S.1½°W., 540 lks. dist.  
A Pine 15" dia., bears N.25°E., 87 lks. dist.  
A W.Oak 5" dia., bears S.10°E., 9 lks. dist.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew  
Aug. 1968 - C.S. File 53/67-1

-----  
Found - Orig. 15" now 28" Fir, alive, N.47°W., 24.4 ft.,  
open, scribe visible.  
Orig. 30" now 54" Fir, alive, S.1½" W., 356.4 ft.,  
open, scribe visible.  
We do not find SE. BT.  
Orig. 15" now 30" Pine, alive, N.25°E., 57.4 ft.,  
open, scribe visible.

Set Brass cap at cor. mkd: County Surveyors Office  
R T 30 S R  
9 S 25 | S 30 8  
W S 36 | S 31 W  
1968

New BTs- 9" D.Fir S.52°E., 16.2 ft. mkd. T30S R8W S31 CS BT  
11" W.Oak N.65°E., 34.2 ft. mkd. T30S R8W S30 CSBT  
8" W.Oak N.10°W., 30.0 ft. mkd. T30S R9W S25 CS BT  
8" D.Fir S.82°W., 26.6 ft. mkd. T30S R9W S36 CS BT  
Corner lies on steep, SW. slope.

Fd. BC & 7 BTs by Don Garrett - For: US Dept. Interior, BLM,  
contract No. 53500-CT2-334(N) - Sept 1972 Filed 2/10/1982  
(added to record 10/2/2023)- M91-10

Douglas Co. Surveyors Office - Gregory Quibell, Deputy - John  
Powell; Randy Smith, crew - Dec. 13, 1982 - C.S. 62/1-34

-----  
Found - 1" x 30" iron pipe with properly mkd. 1968 DCSO  
attached standing loosely approx. 4" in the  
ground.  
Orig. 15" now 28" Fir bears N.43°W., 24.4 ft. (Rec.  
N.47°W.) with pitched over previously opened  
blaze.  
Orig. 30" now 54" Fir with scribed "BT" in  
previously opened blaze, alive. Did not take  
bearing and dist. since it would have required  
cutting many trees out of line of sight and I had  
6 other BTs close to corner. (Cont. Next Page)

TOWNSHIP 30 RANGE 09 POINT IDENTIFIER # 700200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 25 & 36; 30 & 31, T30-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Orig. 15" now 32" Pine with pitched over previously opened blaze bears N.28°E., 57.4 ft. (Rec. N.25°E.)

9" Fir now 10" with well healed single blaze bears S.52°E., 16.2 ft.

11" W.Oak with scribed "S R8W S30 CS BT" in partially healed blaze bears N.65°E., 33.6 ft. (Rec. 34.2 ft.)

8" now 9" W.Oak with scribed "T30S R9W S25 CS BT" bears N.10°W., 30.0 ft.

8" now 10" Fir with well healed single blaze, bears S.82°W., 26.6 ft.

Root hole and rotted remains of possible orig. 5" Oak with no scribing or face visible. Root hole bears S.22°E., 6.4 ft. (Rec. S.10°E., 5.9 ft.)

Since the location I found the brass cap at fit all the trees well, I reference its location and RESET the pipe 24" into the ground and add the marks "RESET 1982" to the cap. Blaze line runs N. from corner to road 30-9-24.1.

---

Cor. Fd. and Used in BLM resurvey by Wayne L. Rogers; Dale T. Bedell; Boyd W. Peterson, Cadastral Surveyors - under Group #1339, surveyed Aug./Nov. 1986 - (DCSO records Vol. 48 Page(s) 18354)

---

BLM survey by Scott Toldness - PLS 90216 - Glahe & Associates Professional Land Surveyors - 2024 - M185-28

-----

Found - Per record all found ok with the exception of:  
A dead and down Fir 54" diam, bears S.1½°W. 359.6' (540 lks) with hacked open face.

Set - 12" Madrone, bears N.52½°E. 31.9' to a nail, scribed "T30SR8WS30BT" with LS washer 90216 and tag by ES 24 and tag on rev replaced tags on S.E. and S.W. BT.

New - Added paint, blazes, nails at right side center, and tags to rev of BTs.  
Added paint, blaze, and tag to the dead and down fir and paint and tag to the stump.

---

2