

TOWNSHIP 31 RANGE 01E POINT IDENTIFIER # 340700

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 & 33, T30-1E

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Fred Mensch, US Deputy Surveyor, under contract dated June 7, 1922 - (DCSO records Vol. 26 Page(s) 11195)

-----  
Set an iron post, 3 ft. long, 1" dia., 27" in the ground, for 1/4 sec. cor., with brass cap marked

1/4  $\frac{S\ 33}{S\ 4}$   
1923

from which

A fir, 20" dia., bears N.58°E., 5 lks., mkd: 1/4 S33 BT.

A fir, 26" dia., bears S.1°W., 19 lks., mkd: 1/4 S4 BT.

-----  
USFS Jim Landrum & Leonard Herzstein - Dec. 22, 1983 - C.S. File 62/15-2

-----  
CONDITION REPORT ONLY

Found - 1" dia., iron post, firmly set with brass cap (properly) marked, established by GLO in 1923.

This corner position appears to be lost. Orig. BTs were destroyed during road construction and monument was reset following construction without being referenced out.

Note - Corner monument is in road fill (USFS Rd# 2925-600) on north side of road.