

PRIMARY CORNER DESCRIPTION Cor. Secs. 7, 8, 17, & 18

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Dennis Hathorn, US Deputy Surveyor, contract 73 dated June 8, 1857 - (DCSO Records Vol. 18 Page(s) 7475-6

Set post, cor. secs. 7, 8, 17, & 18, from which
An oak, 12" dia., bears S.55°W., 99 lks.
An oak, 12" dia., bears N.12°W., 112 lks.
An oak, 15" dia., bears S.45°E., 150 lks.
An oak, 15" dia., bears N.38°E., 88 lks.

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & Terry Connell - Sept. 9, 1966 - C.S. File 54/28-8

Found - 12" B.Oak, now 26", S.55°W., 65.3 ft., shows scar.
15" Oak, now down, S.45°E., 99.0 ft. scribe fd "BT"
15" Oak, now down, N.38°E., 58.1 ft.
12" Oak, now down, N.12°W., 73.9 ft.
Set - Brass cap at cor. mkd: COUNTY SURVEYORS T31S R1W
OFFICE S 7 | S 8
1966 S 18 | S 17
New BTs- 13" D.Fir N.47°E., 26.3 ft. mkd. T31S R1W S8 CS BT.
14" Laurel N.62°W., 17.0 ft. mkd. T31S R1W S7 CS BT.
12" D.Fir S.37°W., 28.1 ft. mkd. T31S R1W S18 CS BT.
13" D.Fir S.50°E., 52.0 ft. mkd. T31S R1W S17 CS BT.

Fd. Ok 12/1977 - M65-60
Fd. Ok (1966 SE BT now stump) by L. Herzstein, USFS, 1/17/1984 - C.S. File 62/15-18

Les Fanning - 2/2001 - C.S. File 65/36-10

Condition Report
Found - 1" galv. iron pipe exposed 12" above ground in a 36" dia. stone mound with a 2½" dia. brass cap firmly affixed to the top stamped as per rec.
From which OBT:
Was 18" now 26" B.Oak snag bears S.55°W. (Rec.) 65.3 ft. (Rec.) with a good face scar.
BTs mkd. by Powell:
Was 13" now 20" D.Fir bears N.47°E. (Rec.) 26.31 ft. (Rec.) with healed face.
Was 14" now 20" Laurel bears N.59°W. (Rec. N.62°W.) 17.0 ft. (Rec.) with healed face.
Was 12" now 16" D.Fir bears S.37°W., (Rec.) 28.1 ft. (Rec.) with healed face.
Was 13" now 13" high stumped D.Fir bears S.50°E. (Rec.) 52.0 ft. (Rec.) with good face scar.
No suitable trees available in Sec. 17
continued next page

PRIMARY CORNER DESCRIPTION Cor. Secs. 7, 8, 17, & 18

Alias	Description
Alias	Description
Alias	Description
Alias	Description

All BTs were painted with a red 6" band & faces.
F.S. sign 54-9 attached to the back of each tree. BT tags were updated or replaced.
Magnetic decl. 20°E.

BLM dependent resurvey by Leonard E. Herzstein, LS USFS, under Group No. 2013, surveyed May 2002/Feb. 2003 - (DCSO records Vol. 54 page(s) 20783-4

The cor. of secs. 7, 8, 17, and 18, perpetuated by the Douglas County Surveyor's Office in 1966; monumented with a 1½" dia. iron post, firmly set, projecting 12" above ground and in a 3 ft. dia. mound of stones, with a brass cap (properly) mkd.
from which the remaining original bearing tree
A B.Oak stump, 24" dia., bears S.55°W., 64.3 ft. no scribe marks visible on hollow open blaze. (Rec. 65.3 ft.) and bearing trees mkd. by County Surveyor in 1966
A D.Fir, 20" dia., bears N.47°E., 26.0 ft., with healed double blaze.
A D.Fir stump, 15" dia., bears S.50°E., 51.6 ft., with healed double blaze.
A D.Fir, 16" dia., bears S.38°W., 27.2 ft., with healed double blaze.
A madrone, 20" dia., bears N.59½°W., 16.7 ft., with healed double blaze.
and a new bearing tree
An I.Cedar, 13" dia., bears S.23¾°E., 182.7 ft., mkd. T31S R1W S17 BT.
Corner point lies N., 4.0 feet of the remaining barbed wire fence corner, downed fences bear N & E.

Jonathan B. Drew, II, USFS - Assisted by: Lance Goucher - 4/22/2015 - C.S. File 65/90-23

Found - A 2½" brass cap on 1¼" galvanized iron pipe, projecting 17" above a mound of stone.
No trace fd of (12" oak) 1857 (24" B.Oak stump) 2003, rec. (S.55°W., 65.3 ft.) 1857 (64.3 ft.) 2003
No trace fd of (12" oak) 1857 (18" oak windfall) 1977
No trace fd of a (15" oak) 1857, (15" down oak) 1966
No trace fd of a (15" oak) 1857, (24" oak windfall) 1977
A 21" fir with a healed double blaze, rec. (N.47°E., 26.3 ft) 1966, (26.0 ft) 2003
A 23" madrone with a faint healed double blaze, rec. (N.62°W., 17.0') 1966, (N.59°30'W., 16.7') 2003
A 16" fir high stump with a healed double blaze, rec. (S.37°W., 28.1') 1966, (S.38°W., 27.2') 2003 cont.

TOWNSHIP 31 RANGE 01 POINT IDENTIFIER # 200500

PRIMARY CORNER DESCRIPTION Cor. Secs. 7, 8, 17, & 18

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

An indeterminate sized rotten fir stump with no marks visible, rec. (S.50°E., 52.0 ft) 1966, (51.6 ft) 2003

A 15" cedar with scribe visible on a partially healed single blaze, rec. (S.23°45'E., 182.7 ft) 2003

New - Missing live tree in SW quad, recent clearing, no suitable trees within no new measurements taken 3 chain limit. Existing high stump is in good condition.

Corner maintenance/other info - clear brush from around monument and to BTs. Tie flagging to monument and guard posts, paint BT faces & a 6" band at head height, add new nails to existing BT Tags & add new tags where needed.

Geodetic coordinates -
LAT: N.42°53'14.706 LONG: W.122°51'48.647"

Datum - WGS 84

Source - USGS QUAD MAP, for navigation to corner.