

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 32 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 18 Page(s) 7460)

Set ¼ sec. post, from which
A Cedar 15" dia., bears S.80°W., 12 lks. dist.
A Fir 18" dia., bears N.89½°W., 33 lks. dist.

GLO Survey by Rufus S. Moore, Deputy Surveyor, under Contract #475, dated July 3, 1883 - (DCSO records Vol. 18 Page(s) 7490)

The old ¼ sec. cor. which is a decayed post, with 1 bearing tree still standing, which is a Fir. I destroyed this post and replaced it with a new Cedar post, 3 ft. long, 3" sq., 24" in the ground mkd. ¼ on S. and N. faces, from which
A Fir 20" dia., bears N.89½°W., 33 lks. dist. mkd. ¼ S BT.
A Cedar 18" dia., bears S.30°E., 35 lks. dist. mkd. ¼ S BT
Could find no traces of Cedar described as bearing tree in field notes of original survey, it having been destroyed by fire, or has fallen and decayed.

Douglas Co. Surveyors Office - James Byron, Deputy - Ray Irving, crew - July 27, 1953 - C.S. File 45/176

Found 1/2" Iron pipe, checks old BT snag still standing, recorded as 18" Cedar, should be 12" Cedar.
Blazed and scribed:
A 10" W.Fir N.10°W., 16.5 ft. mkd. "¼ S32 CS BT"
A 30" Cedar N.70°E., 4.5 ft. mkd. "¼ S32 CS BT"

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Dec. 15, 1964 - C.S. File 53/15-14

Found - Snag on one BT in place, other BT down & out of place.
1/2" I.P. pulled out and laying at approx. corner.
10" now 12" W.Fir snag, N.10°W., 16.5 ft., shows scribe. This snag 6 ft. tall.
Set Brass cap at cor. mkd: County Surveyors Office
T 31 S R 1 W
1/4 S 32
T32S
New BTs- 9" W.Fir N.78°E., 54.9 ft. mkd. ¼ S32 CS BT.
12" D.Fir N.48°W., 58.0 ft. mkd. ¼ S32 CS BT.
This cor. lies 165 ft. East of the CC of secs. 5 & 5, T32S R1W.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION So. 1/4 cor. for Sec. 32 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Survey by Kurt Weaver - For: U.S. Forest Service - Dec. 1979
M 81-58

Found - Brass cap at corner.
D.Fir stump, 12" dia., bears N.48°01'W., 57.3 ft.
(Rec. N.48°W., 58.0 ft.)
W.Fir 13" dia., bears N.79°03'E., 54.0 ft. (Rec.
N.78°E., 54.9 ft.)
Stump hole with dead and down W.Fir bears N.8°47'W.,
16.5 ft. (Rec. N.10°W., 16.5 ft.)
New BTs- 6" dia. Yewwood, bears N.52°05'W., 47.1 ft.
7" dia. D.Fir bears N.57°45'E., 44.6 ft.
13" dia. W.Fir bears N.16°22'W., 62.5 ft.
Corner lies 165 ft. East of the CC of secs. 5 & 6, T32-1W

Ron Quimby - For: WLR Properties LLC - 2/2006 - M149-53

Found - DCSO brass cap
6" Yew bears N.52°W., 47 ft.
16" Fir bears N.61dE., 44.6 ft.
New BTs- 8" Fir bears N.9°W., 27.8 ft. scribed ¼ S32 BT.
9" Cedar bears S.23°E., 30.2 ft. scribed ¼ S32 BT.

Ron Quimby - For: Cow Creek - Nov. 2017 - M171-36

Found - Brass cap per 1964 renewal
12"x6' tall fir stump bears N.48°W., 57.3' (N.48°W.,
58.0') healed scribe
7" now 19" D.Fir bears N.61°E., 44.6' (N.57°45'E.,
44.6') healed scribe
9" now 10" Cedar bears S.23°E., 30.2' healed scribe
6" now 8" Yewwood bears N.52°W., 47.0' (N.52°05'W.,
47.1') healed scribe
8" now 9" Fir bears N.9°W., 27.8' healed scribe