

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Leland P. Lovejoy - For: Mr. L.E. Gilliam - completed March 18, 1953 - C.S. File 41/159

Found corner monuments as shown on map. Set 3/4" G.I. Pipe for 1/4 sec. corner monument of sec. 5, in accordance with procedure prescribed by law.

Douglas Co. Surveyors Office - John M. Powell, and crew - July 25, 1968 - C.S. File 54/71-1

Found - 3/4" Iron pipe (prorated by Leland P. Lovejoy #262, see map filed as C.S. File 41/159. No trees set)
New BTs- 6" W.Fir S.28°E., 19.4 ft. mkd. 1/4 S5 CS BT.
7" W.Fir S.38°W., 16.6 ft. mkd. 1/4 S5 CS BT.
Cor. lies at fence corner, fences E & S, also 159 ft. West of SE Cor. Sec. 32, T31-1.

Survey by Kurt Weaver, #1679 - For: U.S. Forest Service - Feb. 1980 - C.S. File 58/176-34

Found - The 3/4" GIP as set by Lovejoy.
8" W.Fir bears S.39°03'W., 18.0 ft. (Rec. S.38°W., 16.6 ft.)
8" G.Fir bears S.31°00'E., 19.0 ft. (Rec. W.Fir, S.28°E., 19.4 ft.)
2" GIP with a 2 1/2" B.C. at the sec. cor. for secs. 32 & 33, T31S R1W bears S.89°52'48"E., 158.37 ft.
I SET a 2" x 30" GIP with a 2 1/2" brass cap over found pipe exposed 16" in a mound of stone and marked: T31S R1W
1/4 _____
S 5
T32S R1W
SL 1679 1980

John Ransom, USFS - Jonathan Drew - 12/2013 - C.S. 65/85-28

Found - 2 1/2" brass cap (properly mkd) on 2 1/4" iron pipe, projecting 3" above the ground.
13" Fir (S.38°W.) (15.6 ft) healed single blaze.
13" Fir (S.28°E.) (19.4 ft) healed single blaze
Brass cap (S.89°20'28"E.) (158.46 ft) section corner for 33 & 32 only
() = record measurement per RM3-37
No new accessories established
Measure dist to SW BT to determine which rec matches the tree best. Conflicting records red paint applied to BT faces & a 6" band at head height, BTs include BT & survey monument tags Cont.

TOWNSHIP 31 RANGE 01 POINT IDENTIFIER # 278100

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. for Sec. 5 only, T32-1

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Brush cleared around monument and to BTs
"LAND LINE" flagging tied on monument & guard posts
Note - Corner falls on north slope under a barbed wire a few feet east of a large fir tree fence corner. Park at dispersed campsite on south side of FS road 150 just prior to first cattle guard, walk south to fence line then west to corner. Maintain line .5 miles south.

Adam DeGroot - For: USFS - Oct 2019 - M171-69A&B

Found - A 2¼" iron post by Weaver, in 1980 per C.S. File 58/176-34, firmly set and projecting 8" above ground in an 18" diam. stone mound, with a 2 1/2" brass cap (properly) mkd:

BTs by DCSO IN 1968 -

A 13" G.Fir bears S.31°E., 18.9 ft w/healed dbl blaze (S.28°E., 19.4 ft-DCSO 1968) (S.31°00'E., 19.0 ft-Weaver 1980)

A 14" W.Fir bears S.38°'15'W, 15.5 ft w/healed dbl blaze (S.38°W., 16.6 ft-DCSO 1968) (S.39'03'W., 18.0 ft-Weaver 1980)

New RM - A 5/8"X30" iron rod w/2" alum. cap mkd. "BTS SURVEYING INC RM 1 PLS 89398" bears N.31°00'03"W., 19.67 ft

The section corner of S32/S33 bears S.89°50'26"E., 158.28 ft (line of sight)

A 6"x10" split cedar fence corner of fences east and south bears S.50'E., 2.0 FT

Fd. OK by DCSO (SJF & JL) 6/3/2020 - C.S. File 67/46-33

Lat: 42.828683450 Long: -122.844203217