

PRIMARY CORNER DESCRIPTION Cor. Secs. 4, 5, 8, & 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, US Deputy Surveyor, contract 73 dated June 8, 1857 - (DCSO Records Vol. 18 Page(s) 7470-1

Set post, cor. secs. 4, 5, 8, & 9, from which
A hemlock, 6" dia., bears S.60°E., 50 lks.
A hemlock, 9" dia., bears S.55°W., 42 lks.
A hemlock, 6" dia., bears N.15°W., 35 lks.
A fir, 24" dia., bears N.80°E., 39 lks.

GLO survey by Fred Mensch, US Cadastral Engineer - Under special instructions dated June 7, 1922 - (DCSO records Vol. 18 Page(s) 7547)

The cor. of secs. 4, 5, 8, & 9, which is a badly decayed post, with marks indecipherable; from which
A fir, 30" dia., bears N.83°E., 30 lks., mkd: T31S R1W S4 BT. (Old BT)
A hemlock, 14" dia., bears S.57°E., 50 lks., mkd: T31S R1W S9 BT. (Old BT)
A hemlock, 18" dia., bears S.57°W., 42 lks., mkd: T31S R1W S8 BT. (Old BT)
A hemlock, 18" dia., bears N.12°W., 35 lks., mkd: T31S R1W S5 BT. (Old BT)
In place of the decayed post
Set an iron post, 3 ft. long, 2" dia., 28" in the ground, for cor. of secs. 4, 5, 8, & 9, with brass cap mkd
T31S R1W
S 5|S 4
S 8|S 9
1923

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & W. Penley - Sept. 1968 - C.S. File 54/71-47

Found - GLO Brass Cap, properly marked in 1923.
30, now 38" D.Fir, N.83°E., 19.8 ft., shows good scar.
14", now 17" Hemlock, S.57°E., 33.0 ft., shows good scar.
18", now 22" Hemlock, S.57°W., 27.7 ft., shows good scar.
18", now down Hemlock, N.12°W., 23.1 ft.
New BT - 8" Hemlock N.43°W., 44.0 ft. scribed T31S R1W S5 CS BT.