

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 28

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

John Ransom, USFS - Crew: Jonathan Drew - 7/28/2014 (filed 3/29/2017) - C.S. File 65/95-16

Found - 26" fir corner tree with healed double blazes on east and west side, also a 2½" brass cap on 1¼" iron pipe on south side in small ring of stone, slanted south by tree growth.

2.5" brass cap south 2 ft reference monument

16" Fir snag (S.5°E.) (36.5 ft) 8 ft tall snag, healed double blaze.

13" fir stob S.17°30'W., 29.5 ft rotten stob, healed single blaze

() = record per CS 62/30

New - A 21" Cedar bears, N.61°W., 66.4 ft, mkd "¼S28" "BT" on a double blaze.

A 13" Fir bears, S.78°30'E., 35.2 ft, mkd "¼S27" "BT" on a double blaze.

A 7" Fir bears, S.29°15'E., 13.1 ft, mkd "¼S27" "BT" on a double blaze.

A 6" Fir bears, S.16°15'W., 24.2 ft, mkd "X" "BT" on a double blaze.

All new accessories include 3/4" brass washer stamped "LS2561" nailed in lower face between "B" & "T"

Note - Corner falls at the base of a slope, on a high bench above creek to the south, fallen down fences come into corner from south and west. Take FS road 370 to pull out just north of corner, hike south down south slope to corner.

Maintained property line .5 miles south and west
Brush cleared around monument and to BTs "LAND LINE" flagging tied on monument and guard posts.

Measurements to accessories made with a LEICA 1103+ Total Station with reflectorless EDM to aluminum nail set at side center, basis of bearing from M50-33, being N.89°24'44"W., as set using a property line post found to the west 250 ft+/-.