

PRIMARY CORNER DESCRIPTION North 1/4 Cor. Sec. 34 only

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>GLO survey by Dennis Hathorn, US Deputy Surveyor, contract 73 dated June 8, 1857 - (DCSO Records Vol. 18 Page(s) 7464</p> <p>-----</p> <p>Set ¼ sec. post, from which An Oak, 12" dia., bears N.40°E., 130 lks. An Oak, 15" dia., bears S.17°E., 139 lks.</p>
<p>GLO survey by Fred Mensch, US Cadastral Engineer - Under special instructions dated June 7, 1922 - (DCSO records Vol. 18 Page(s) 7537)</p> <p>-----</p> <p>The point for the ¼ sec. cor. established for secs. 27 & 34, which I determine by reference to the orig. BT. I now change this cor. to refer to sec. 34 only. Set an iron post, 3 ft. long, 1" dia., 28" in the ground, for ¼ sec. cor. of sec. 34 only, with brass cap marked</p> <p style="text-align: center;">¼ S34 ----- 1923</p> <p>from which A fir, 8" dia., bears S.75°E., 52 lks., mkd: ¼ S34 BT. (New BT) A fir, 10" dia., bears S.36°W., 27 lks., mkd: ¼ S34 BT. (New BT) A dead oak, 15" dia., bears S.17°E., 139 lks., mkd: ¼ S BT. (Old BT) The orig. BT referring to sec. 27 is dead & fallen.</p>
<p>Fd. BC & 2 BTs by D. Garrett, 8/1975 - M58-7</p>
<p>Douglas Co. Surveyors Office - John M. Powell - Frank Jones & W. Penley - Sept. 1968 - C.S. File 54/71-53</p> <p>-----</p> <p>Found - GLO Brass Cap, properly marked in 1922. 10", now 17" D.Fir, S.36°W., 17.8 ft., shows good scar. 8", now D.Fir burnt stob, S.75°E., 34.3 ft. New BT - 6" W.Fir S.50½°E., 60.0 ft. scribed "¼ S34 CS BT" Note - ¼ Corner of Section 27, bears E. 49.5 ft. Also fence bears North 5.0 ft.</p>
<p>John Ransom, USFS - Jonathan Drew - 1/2013 - C.S. 65/85-21</p> <p>-----</p> <p>Found - 2½" brass cap (properly mkd) on 1" iron pipe, projecting 14" above the ground. Monument leans W-NW 33" D.Fir (S.38°11'W.) (17.7 ft) healed single high blaze.</p>

continued next page
TOWNSHIP 31 RANGE 01 POINT IDENTIFIER # 439200

PRIMARY CORNER DESCRIPTION North 1/4 Cor. Sec. 34 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

12" Fir stump (S48°40'W) (59.9 ft) 6.5' high stump, rotten face, no bark
2.5" brass cap (S.88°05'E.) (49.05 ft) 1/4 S27 only
GLO cap per M58-7
() = RECORD PER M83-4
Brush cleared around monument and to BTs
"LAND LINE" Flagging tied on monument and guard posts.
No new accessories added
New nails in BT tags and painted faces & 6 inch band at head height
Note - Corner falls on slight west slope, just south of old barbed wire fence, on edge of timber line with old growth to the north. To find corner, take 1610-370 about 500 ft past the 378 spur, go south on old overgrown road above rock erosion control on edge of road, follow old road to posted line, then east on line.
Property line maintained west 1700 ft ± and east .5 mile.