

PRIMARY CORNER DESCRIPTION Cor. Secs. 26, 27, 34, & 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, US Deputy Surveyor, contract 73 dated June 8, 1857 - (DCSO Records Vol. 18 Page(s) 7463

Set post cor. secs. 26, 27, 34, & 35, from which
A fir, 20" dia., bears N.50°W., 56 lks.
A fir, 12" dia., bears N.30°E., 36 lks.
A fir, 24" dia., bears S.38°W., 11 lks.
A fir, 36" dia., bears S.10°E., 38 lks.

GLO survey by Fred Mensch, US Cadastral Engineer - Under special instructions dated June 7, 1922 - (DCSO records Vol. 18 Page(s) 7535-6)

The cor. of secs. 26, 27, 34, & 35, located by reference to the orig. BTs, 445 ft. above ¼ sec. cor.

At exact cor. point

Set an iron post, 3 ft. long, 2" dia., 28" in the ground, for cor. of secs. 26, 27, 34, & 35, with brass cap mkd

T31S R1W
S 27 | S 26
S 34 | S 35
1923

from which

- A fir, 12" dia., bears N.30°E., 36 lks., mkd: T31S R1W S26 BT. (Old BT)
- A fir, 36" dia., bears S.10°E., 38 lks., mkd: T31S R1W S35 BT. (Old BT)
- A fir, 24" dia., bears S.38°W., 11 lks., mkd: T31S R1W S34 BT. (Old BT)
- A fir, 20" dia., bears N.50°W., 56 lks., mkd: T31S R1W S27 BT. (Old BT)

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & W. Penley - Aug. 1968 - C.S. File 54/71-116

Found - 1922, GLO Brass Cap, properly marked.
12" D.Fir, now rotten stump, N.30°E., 23.8 ft. found scribe.
36" D.Fir, now snag, S.10°E., 25.1 ft., shows good scar.
20", now 36" D.Fir, N.47°W., (Rec.N.50°W.) 37.0 ft., shows good scar.
24" D.Fir, flow down & rotten, S.38°W., 7.3 ft.
New BTs- 34" D.Fir N.66°E. 40.6 ft. scribed T31S R1W S26 CS BT
12" R.Fir S.24½°E. 18.0 ft scribed T31S R1W S35 CS BT
No trees available in S. W. Quad, ok unit.

continued next page

TOWNSHIP 31 RANGE 01 POINT IDENTIFIER # 500200

PRIMARY CORNER DESCRIPTION Cor. Secs. 26, 27, 34, & 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Don Garrett - For: USFS - Aug. 1975 - M58-7

Found - Brass cap stamped USGLO Survey 1922, S26, S27, S34,
S35 T31S R1W
40" fir bears N.47°W., 37.0 = 11.278 M
34" fir bears N.66°E., 40.6 = 12.375 M
14" fir bears S.24½°E., 18.0 = 5.486 M
No trees available in old unit in SW quadrant.

John Ransom, USFS - Jonathan Drew - 1/2014 - C.S. 65/85-23

Found - 2½" brass cap (properly mkd) on 2" iron pipe,
projecting 7" above a mound of stone.
41" Fir (N.47°W.) (37.0 ft) healed double blaze
36" Fir (N.66°E.) (40.6 ft) healed double blaze
25" Fir (S.24°30'E.) (18.0 ft) healed single blaze
Indt. Root hole (S.38°W.) (7.3 ft) root hole found,
log rotten
43" Fir snag (S.10°E.) (25.1 ft) healed double blaze
Indt. Fir stump (N30°E) (23.8 ft) no marks found
() = record per M58-7 & C.S. 54/71

Bearings to fd accessories checked well with hand
compass, bearing to new tree by hand compass.
Distances to fd accessories is record, distance
to new tree by steel tape
New - A 10" Fir bears S.63°W. - 17.3 ft, scribed "T31S R1W
S34" "BT" on double blaze with 3/4" brass washer
mkd "LS2561" nailed between B&T in lower blaze
New nails in BT tags and painted faces & 6" band at
head height

Brush cleared around monument and to BTs
"LAND LINE" flagging tied on monument & guard posts
Note - Corner falls at toe of steep east slope, on nearly
level bench. To access corner take 1610-500 road
to 1610-540 spur, park and walk southeast 700
feet +/- to corner or south to posted line then
east to corner.
Property line maintained west 4393 ft +/-

Fd. BC & BTs 6/8/2015 by Jonathan Drew II, C.S. File 65/90-61
Lat: N.42°50'35.794 Long: W.122°48'13.279"
Source: Cell phone GPS, for navigation to corner.