

TOWNSHIP 31 RANGE 02 POINT IDENTIFIER # 100140

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. for Sec. 31 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. -
July 29, 1955 - C.S. File 42/23

At Corner point, SET a 1" x 30" Iron pipe, from which
A 13" Fir bears N.75°E., 21.5 ft. mkd. ¼ S31 BT.
A 5" Hemlock bears S.51°E., 7.0 ft. mkd. ¼ S31 BT.
E. ¼ cor. Sec. 36, T31S R3W., bears South 435.0 ft.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones &
T. Connell, crew - Aug. 1966 - C.S. File 54/28-94

Found - 1" I.Pipe at corner.
13" now 14" Fir N.75°E., 21.5 ft., shows good scar.
5" now 11" Hemlock S.51°E., 7.0 ft. scribe visible
"BT".

Set Brass cap at cor. mkd: County Surveyors office

R	T	31	S	R	
3	¼		S	31	2
W				W	

1966

Bearing trees all OK. This corner is North of rock pit in
small draw. ¼ Cor. S. 36 only is gone. It lies in rock pit
435.0 ft. S. of this ¼ cor.

Gerald V. Nygren - April 21, 1988 - C.S. File 63/69-23

Found - 1" galv. I.P. with 2½" brass cap extended 9" above
ground and mkd. 1966 DCSO.
1" I.P. to the SW. and alongside brass cap.
14" D.Fir snag bears N.76°29'E., 21.5 ft., healed
blaze.
19" Hemlock bears S.49°41'E., 7.2 ft., healed blaze.
New BT - 20" W.Fir bears N.43°E., 11.9 ft. scribed "T31S R2W
¼ BT", double blaze. Set ½" brass washer in lower
blaze.

Bearing tree signs and monument signs were placed on all BTs
without them and a 6" red band and face blazes were painted
on all bearing trees.