

TOWNSHIP 31 RANGE 02 POINT IDENTIFIER # 100600

PRIMARY CORNER DESCRIPTION CC for Secs. 6 & 7 only, (West)

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by Fred Mensch, Deputy Surveyor, under Contract #766, dated May 1906 - (DCSO records Vol. 18 Page(s) 7666)

-----  
Set an ironstone 14x10x6 ins., 9½" in the ground for closing cor. of secs. 6 & 7 marked CC on E. with 1 groove on N. and 5 grooves on S. face, from which

A Cedar 30" dia., bears N.49°E., 74 lks. dist. mkd. T31S R2W S6 BT.

A Fir 24" dia., bears S.69°E., 34 lks. dist. mkd. T31S R2W S7 BT.

Destroy marks on bearing trees a former cor. referring to secs. 6 and 7.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & W. Penley, crew - March 25, 1970 - C.S. File 54/28-98

-----  
Found - 14x10x6 stone at corner, no marks visible.  
30" Cedar now stump N.49°E., 48.8 ft. scribe visible.

24" now 36" Fir S.69°E., 22.4 ft., shows scar.

Set Brass cap at cl. cor. mkd: County Surveyors Office

R	R	31	S	R	
3			S	6	2
W	CC		S	7	W
1970					

New BT - 12" W.Fir N.7°E., 40.3 ft. mkd. T31S R2W S6 CC CS BT  
Reblazed and rescribed:

36" D.Fir S.69°E., 22.4 ft. mkd. T31S R2W S7 CC CSBT

This corner lies 215.2 ft. North of cor. for 1 & 12, T31-3

Ron Quimby - For: Roseburg Resources Co - Dec. 2014 - M166-27

-----  
Found - Brass cap per 1970 DCSO renewal  
19" Fir N.7°E., 40.3' healed face  
37" Fir S.69°E., 22.4' healed face  
4' Tall - 30" Cedar stump N.49°E., 48.8' visible scribe

New - 10" W.Fir S.59°E., 19.1' scribed "T31S R2W CC S7 BT"  
18" D.Fir N.44°E., 54.8' scribed "T31S R2W CC S6 BT"

Ron Quimby - 9/2015 - C.S. File 65/89-40

-----  
Corner updates Sec. 6 T31S R2W. due to burn 8/2015 - Corner Data on M166-27.

New BT - 5" Fir S.43°E., 15.7 ft. scribed T31S R2W S7 BT.

Added spikes to side-center of all trees