

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 6 and 7

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #766, dated May 10, 1906 - (DCSO records Vol. 18 Page(s) 7666)

Set a granite stone 18x8x8 ins., 12" in the ground for ¼ sec. cor. marked ¼ on N. face, from which
A Fir 30" dia., bears N.67°W., 25 lks. dist., mkd. ¼ S6 BT
A Fir 36" dia., bears S.70°W., 17 lks. dist., mkd. ¼ S7 BT

Corner report by Dennis Gaylord, U.S. Forest Service (Deputized by the County) Wit: Roland Smishauser - Dec. 8, 1977 - C.S. File 59/42-25

Found - A stone 16"x8"x6", firmly set in the ground. No markings visible on the stone.
A 44" orig. 36" D.Fir, nearly ded, bears S.70°W., 11.22 ft. Has a healed scar.
A 31" orig. 30" D.Fir stump, bears N.67°W., 16.0 ft. (Rec. 16.5 ft.) Has a healed scar.
Placed County BT signs on both trees.
Referencing the stone monument, I remove stone and set in its place a 2½" brass cap on a 1" galv. I.P. mkd. "County Surveyors Office T31S R2W ¼ S6 S7 1977". I bury the orig. corner stone alongside the brass cap.
New BTs- 25" D.Fir bears S.53°W., 57.5 ft. scribed "¼ S7 CS BT" on a double blaze.
9" D.Fir bears N.50°30'E., 38.3 ft. scribed "¼ S6 CS BT" on a double blaze.
Placed County BT signs on both trees.

Ron Quimby - For: Roseburg Resources Co - Dec. 2014 - M166-27

Found - Stone per 1906 GLO Survey & brass cap per 1977 U.S.F.S. renewal
44" Fir S.70°W., 11.2' healed face.
30" Fir stump (rotten) N.67°W., 16.0'
28" Fir S.53°W., 57.5' mostly healed face
17" Fir N.50°E., 38.3' fully healed face
New - 13" Fir N.50°W., 25.4' scribed "¼ S6 BT"

Ron Quimby - 9/2015 - C.S. File 65/89-40

Corner updates Sec. 6 T31S R2W. due to burn 8/2015
Corner Data on M166-27.
Added spikes to side-center of all trees