

TOWNSHIP 31 RANGE 02 POINT IDENTIFIER # 200600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5, 6, 7 and 8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #766, dated May 10, 1906 - (DCSO records Vol. 18 Page 7664)

-----  
Set a slate stone 18x12x7", 12" in the ground for cor. of secs. 5, 6, 7 and 8 marked with 5 notches on S & E edges, from which

- A Fir 40" dia., bears N.34°E., 27 lks mkd. T31S R2W S5 BT.
- A Maple 12" dia. bears S.58½°E., 20 lks mkd T31S R2W S8 BT
- A Hemlock 12" dia. bears S.64°W. 27 lks mkd T31S R2W S7 BT
- A Fir 7" dia., bears N.11°W., 30 lks. mkd. T31S R2W S6 BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Terry Connell, crew - Sept. 1966 - C.S. File 54/28-97

-----  
Found - Slate stone at sec. corner.  
40" now 48" D.Fir, N.34°E., 17.8 ft. shows good scar  
12" now 15" Hemlock, S.64°W., 17.8 ft., scribe visible "3 2 T".  
7" now 17" W.Fir, N.11°W., 19.8 ft., shows good scar  
12" Maple, now down, S.64°W., 13.2 ft.

Set Brass cap at cor. mkd: County Surveyors Office  
T 31 S R 2 W  
S 6 | S 5  
S 7 | S 8  
1966

New BT - 9" Hemlock S.82°E., 34.9 ft. mkd. T31S R2W S8 CS BT.  
Rescribed-  
20" Hemlock, S.82°E., 34.9 ft. mkd T31S R2W S8 CS BT  
This corner lies 100 ft. West of Hatchet Creek.

Ron Quimby - For: Roseburg Resources Co - Dec. 2014 - M166-27

-----  
Found - Brass cap per 1966 DCSO renewal  
51" D.Fir N.34°E., 17.8' fully healed face  
26" Hemlock S.64°W., 17.8' rotten scribe  
23" W.Fir N.11°W., 19.8' fully healed face  
15" Hemlock S.82°E., 34.9' mostly healed face

Ron Quimby - 9/2015 - C.S. File 65/89-40

-----  
Corner updates Sec. 6 T31S R2W. due to burn 8/2015 - Corner Data on M166-27.  
New BT - 4" Yew N.50°E., 32.4 scribed T31S R2W S5 BT.  
Added spikes to side-center of all trees.