

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 5 and 6

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #766, dated May 10, 1906 - (DCSO records Vol. 18 Page(s) 7667)

-----  
Set a granite stone 18x14x4 ins., 12" in the ground for ¼ sec. cor. marked ¼ on W. face, from which  
A Hemlock 12" dia., bears S.65°E., 24 lks. dist. mkd. ¼ S5 BT.  
A Fir 12" dia., bears S.51°W., 28 lks. dist. mkd. ¼ S6 BT.

Corner report by Lloyd R. Moffit - For: U.S. Forest Service -Aug. 1978 - C.S. File 58/176-001A

-----  
Found - A granite stone 18"x14"x4", marking the ¼ corner.  
A 20" Fir bears S.51°W., 18.5 ft., shows scar.  
A 20" Hemlock bears S.65°E., 15.8 ft., scribe visible.  
Set a 2" Pipe with 3" brass cap stamped: "T31S R2W ¼ S6 S5 PLS 944 1978".  
New BTs- A 16" Hemlock bears S.10°E., 34.1 ft. scribed ¼ S5 BT.  
The original stone is buried alongside the 2" pipe. The new BT has a brass tag #944 nailed at BT scribe.

Ron Quimby - For: Roseburg Resources Co - Dec. 2014 - M166-27

-----  
Found - Brass cap per 1978 U.S.F.S. renewal  
25" Fir S.51°W., 18.5' visible "X"  
15' tall rotten stump S.65°E., 15.8' visible x and hollow scar  
19" Hemlock S.10°E., 34.1'  
New BOs- 25" Fir N.33°W., 16.0'  
6" Hemlock N.76°W., 15.5'  
Both scribed "¼ S6 BT"

Ron Quimby - 9/2015 - C.S. File 65/89-40

-----  
OK  
Corner updates Sec. 6 T31S R2W. due to burn 8/2015  
Corner Data on M166-27.  
Added spikes to side-center of all trees