

PRIMARY CORNER DESCRIPTION SW Cor. Sec. 16 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 18 Page(s) 7605)

Set post cor. secs. 16, 17, 20 and 21, from which
A Cedar 18" dia., bears N.45°W., 4 lks.
A Yew 12" dia., bears N.5°E., 40 lks.
A Hemlock 15" dia., bears S.2°E., 29 lks.
A Fir 12" dia., bears S.65°W., 153 lks.

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #766, dated May 10, 1906 - (DCSO records Vol. 18 Page(s) 7655)

The old cor. of secs. 16, 17, 20 and 21 is partially obliterated, the post being decayed and the bearing trees overgrown. I reestablish this cor. in its original position as the SW. cor. of Sec. 16 only, as follows:
Set a granite stone 18x8x8 ins., 12" in the ground for SW. cor. of sec. 16, marked with 4 notches on E. edge, from which
A Fir 10" dia., bears N.36½°E., 60 lks. dist. mkd. T31S R2W S16 BT.
Destroy marks on bearing trees referring to secs. 17, 20, and 21.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; Clete Putnam, crew - June, 1961 - C.S. File 52/81-4

Found - Granite rock with 4 notches as called for in govt. field notes.
W.Fir now 30", N.35½°E., 39.6 ft. 39.6 ft., showing 2 good scars, did not chop open.
Alongside rock, Set Iron pipe with brass cap marked:
County Surveyors Office
T 31 S R 2 W
| S 16
SW Cor. Sec. 16
1961
New BT - 15" D.Fir N.82°E., 65.2 ft. mkd. T31S R2W S16 CS BT.

Survey by William Ruppert - For: U.S. Forest Service - Feb. 1979 - C.S. File 58/176-23

Found - 1" Pipe with 1961 DCSO brass cap, properly mkd.
36" Cedar N.82°W., 3.0 ft., scars.
20" D.Fir N.81°E., 65.0 ft., good scar.
Scribed- "T31S R2W S16 BT" on 16" D.Fir N.29½°E., 34.5 ft.
Attached brass washer "LS 866" to lower blaze.