

TOWNSHIP 31 RANGE 02 POINT IDENTIFIER # 300403

PRIMARY CORNER DESCRIPTION C C for Secs. 17 and 21

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #766, dated May 10, 1906 - (DCSO records Vol. 18 Page(s) 7647 and 7655)

-----  
(Page 7647)

Set temp. closing cor. deferring establishment of cors. until closing with the line bet. secs.17 and 20.

(Page 7655)

At a point on the S. bdy. Sec. 16, 3.17 chs. North of the CC of secs. 17 and 20 and 2.83 chs. E. of the old cor. of secs. 16, 17, 20 and 21 - I reestablish closing cor. of secs. 17 and 21, as follows:

No stones available. Set a Fir post 3 ft. long, 4" sq., 24" in the ground for closing cor. of secs. 17 and 21, marked S21 on E.; CC T31S R2W on S.; and S17 on W. face, with 4 grooves on E. face, from which

A Fir 36" dia., bears S.15°E., 27 lks. dist. mkd. T31S R2W S21 BT.

A Fir 6" dia., bears S.6°W., 71 lks. dist. mkd. T31S R2W S17 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; Clete Putnam, crew - June 1961 - C.S. File 52/81-2

-----  
Found - 6" Fir S.6°W., 46.9 ft., down and rotting, found good scribing "BT".

Shattered remnants of 36" Fir, S.15°E., 17.8 ft., no scribing found on this tree.

Set Brass cap at cor. mkd: County Surveyors Office

T 31 S R 2 W

S 16

S17 | S21

1961

New BTs- 10" W.Fir S.15½°W., 13.7 ft. mkd. T31S R2W S17 CS BT.

13" Hemlock S.64°E., 25.1 ft. mkd. T31S R2W S21 CS BT.

(Note: "Sec. 16" stamped on cap, Jan. 1975 by G. Baughman)