

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. for Sec. 16 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 18 Page(s) 7606)

Set ¼ sec. post, from which
A Fir 36" dia., bears N.10°E., 26 lks.
A Fir 24" dia., bears N.5°W., 20 lks.

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #766, dated May 10, 1906 - (DCSO records Vol. 18 Page(s) 7678-79)

The ¼ sec. cor. nearly obliterated. No trace of the post is found. One bearing tree is uprooted and fallen across the other concealed all marks. I reestablish the cor. in its original position as follows:
Set a slate stone 14x10x8 ins., 9½" in the ground for ¼ sec. cor. marked ¼ on W. face, from which
A Fir 18" dia., bears S.32½°E., 35 lks. dist. mkd. ¼ S16 BT.
A Fir 24" dia., bears S.21°W., 27 lks. dist. mkd. ¼ S17 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; Clete Putnam, crew - June 1961 - C.S. File 52/81-1

Found - Rock set by Mensch in 1908, no marking found on rock.
Fir stump, now 22", S.32½°E., 23.1 ft., bottom of lower scar showing.
Fir stump, now 36", S.21°W., 17.8 ft., opened scar and found partial scribe marks.
These stumps are both cut low. Appear to have been cut about 3 years ago.
Alongside rock at corner, Set brass cap marked:
County Surveyors Office
T 31 S R 2 W
¼ S17 | S16
1961
New BTs- 9" Hemlock N.20½°W., 17.1 ft. mkd. ¼ S17 CS BT.
11" I.Cedar N.30°E., 35.1 ft. mkd. ¼ S16 CS BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & W. Penley, crew - Feb. 27, 1970 - C.S. File 54/28-106

Found - 1961 DCSO brass cap. I now destroy everything that refers to sec. 17, so brass cap now reads:
(Cont. Next Page)

TOWNSHIP 31 RANGE 02 POINT IDENTIFIER # 300443

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. for Sec. 16 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

<p>County Surveyors Office T 31 S R 2 W ¼ S 16 1961</p>
<p>Renewed BT: 11" I.Cedar N.30°E., 35.1 ft. mkd. ¼ S16 CS BT. New BT - 21" D.Fir S.83°E., 31.4 ft. mkd. ¼ S16 CS BT.</p>
<p>Survey by Loyd R. Moffit - For: U.S. Forest Service - Nov. 1986 - C.S. File 62/30-20 ----- Found - 1961 DCSO brass cap (2½") on 1" I.Pipe. Fir stump, S.32½°E., 23.1 ft. (1908) 14" Cedar N.30°E., 35.1 ft., scribe visible. Fir stump, S.83°E., 31.4 ft., scribe visible. Fir stump S.21°W., 17.8 ft. (1908) New BT - A 9" Fir which bears N.80½°W., 4.7 ft. scribed ¼ S16 BT with LS washer #944 nailed to BT scribe.</p>
<p>Ray Wytcherly - For: Boise Cascade Corp. - 10/2004 - M145-55 ----- Found - 1961 DCSO brass cap, from which: 1961 County BT, a cedar 22 in. dia. bears (N.30°E, 35.1 ft.) Face healed over. 1986 B.T., (C.S.) File 62/30 a D.Fir 14" dia. bears (N.80½°W, 4.7 ft.) Face healed over New BTs- A D.Fir 10" dia. bears S2°W, 21.55 ft. scribed "S 17 ¼ BT" A D.Fir 6" dia. bears N.88°E., 27.83 ft. Scribed "S16 ¼ BT" A Chinquapin 10" dia. bears N.28°E., 13.36 ft. scribed "S 16 1/4 BT"</p>