

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 34 and 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #766, dated May 10, 1906 - (DCSO records Vol. 18 Page(s) 7639)

Set an ironstone 12x8x6 ins., in the ground for ¼ sec. cor. marked ¼ on W. face, from which
A Fir 20" dia., bears N.38°E., 17 lks. dist. mkd. ¼ S35 BT
A Cedar 18" dia., bears S.87°W., 15 lks. dist. mkd. ¼ S34 BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Terry Connell, crew - June/July 1966 - C.S. File 54/28-26

Found - Iron stone at ¼ corner mkd. "¼" on N. face.
18" Cedar now 24", S.87°W., 9.9 ft. scribe visible "S".
20" Fir, now stump, N.38°E., 11.2 ft.
Set Brass cap at cor. mkd: County Surveyors Office
T 31 S R 2 W
¼ S34 | S35
1966

New BTs- 42" D.Fir ~~N.26°W.~~*N.28°W. 18.6 ft scribed ¼ S34 CSBT
No trees available in Sec. 35.
Corner lies about 60.0 ft. on North side of draw.
*Corrected 9/26/2018 JC DCSO

Leonard Herzstein, U.S. Forest Service (Deputized by the Surveyors Office) Wit: Jim Landrum and Tom Wolford - May 20, 1981 - C.S. File 61/27-2

CONDITION REPORT ONLY
Found - 1¼" I.P. firmly set, projecting 12" above ground with 1966 DCSO brass cap, properly marked.
Orig. stone set alongside with marks "¼" on top.
A rotted D.Fir stump, size indeterminate, N.30°E., 11.2 ft. with no marks visible.
A 24" I.Cedar S.87°W., 9.9 ft. with healed blaze.
42" D.Fir stump N.28°W., 18.6 ft. with scribe marks visible.
BT of which there is no record, a 10" I.Cedar N.18°E., 86.4 ft. with scribe marks visible on partly healed blaze.
(Note: BT put on record Sept. 15, 1981 by B. Shaner, C.S. File 58/229-34)