

TOWNSHIP 31 RANGE 03 POINT IDENTIFIER # 100440

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 18; & 13 of T31-4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7795)

Set a stone 14x10x5 ins., 10" in the ground, for ¼ sec. cor. mkd. ¼ on W. face; from which
A Fir 34" dia., bears S.66°E., 47½ lks. dist. mkd. ¼ S BT
A Fir 18" dia., bears S.48½°W., 26½ lks. dist. mkd. ¼ S BT

Survey by John H. Markham, Jr. - Wit. J.R. Markham - For: Stomar Lumber Co. - Oct. 7, 1959 - C.S. File 42/391-43

Determined by Original BTs:
40" Fir S.66°E., 33.0 ft.
36" Fir S.48°W., 17.4 ft.
At corner point, SET 1½" x 30" Iron pipe, from which
8" Fir bears S.20°W., 26.0 ft. mkd. ¼ S13 BT.
7" Fir bears N.84°E., 23.6 ft. mkd. ¼ S18 BT.
11" Fir bears N.29°E., 24.0 ft. mkd. ¼ S18 BT.
Shively Creek bears South, 100.0 ft.

Fd. OK, Feb. 1981 by H. Johnstone - M 86-42

Douglas County Surveyors Office - Gregory Quibell, Deputy - Debbie Stewart, crew - April 27, 1981 - C.S. File 61/19-50

Found - 1½" x 30" Pipe, firmly set.
Orig. 34" now 40" Fir with BLM BT tag and well healed blaze, lying downhill approx. 30 ft. from its orig. location. Remains of stump hole and root bears S.66°E., 33.0 ft.
Orig. 18" now 35" Fir with well healed blaze, BLM tag and large "X" in bark bears S.48°W., 17.4 ft.
8" now 9" Fir with well healed blaze, bears S.20°W., 24.8 ft. (Rec. 26.0 ft.)
11" now 12" Fir with well healed blaze, bears N.29°E., 24.0 ft.
Remains of 7" Fir scribed ¼ S18 BT visible. Tree is down and rotten. Exact orig. location of tree is not apparent.
New BTs- 9" Madrone scribed "¼ S18 CS BT" in double blaze, bears N.51°E., 42.3 ft.
13" Yew scribed "¼ S13 CS BT" in double blaze, bears N.14°W., 36.0 ft.
Did not set brass cap since area will possibly be destroyed in road construction. Found no trace of original stone.