

TOWNSHIP 31 RANGE 03 POINT IDENTIFIER # 100500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 7 & 18; 12 & 13, T31-4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7795-96)

-----  
Set a stone 14x12x9 ins., 10" in the ground, for cor. to secs. 7, 12, 13 and 18, marked with 2 notches on N. and 4 notches on S. edges; from which

A Fir 45" dia., bears N.26½°E., 72 lks. dist. mkd. T31S R3W S7 BT.

A Fir 28" dia., bears S.8°E., 136 lks. dist. mkd. T31S R3W S18 BT.

A Fir 28" dia., bears S.32°W., 106½ lks. dist. mkd. T31S R4W S13 BT.

A Fir 10" dia., bears N.84°W., 69½ lks. dist. mkd. T31S R4W S12 BT.

Survey by John H. Markham, Jr. - Wit: R.G. Boyd; Keatley and J.L. Markham - For: Stomar Lumber Co. - Oct. 7, 1959 - C.S. File 42/391-42

-----  
Determined by original BTs:

32" Fir S.32°W., 70.3 ft., found scribe.

36" Fir S.8°E., 90.0 ft.

44" Fir N.26°E., 47.5 ft.

32" Fir N.84°W., 46.0 ft.

At corner point, Found stone and SET 3/4" x 30" Iron pipe, from which

7" Fir bears N.6°E., 14.9 ft. mkd. S12 BT.

7" Cedar bears N.40°E., 22.2 ft. mkd. S7 T31S R3W BT.

15" Fir bears S.70°E., 7.0 ft. mkd. S18 R3W BT.

6" Laurel bears S.14°W., 30.0 ft. mkd. S13 T31S R4W BT.

Referenced out for road work by DCSO, Gary Langlitz, Deputy -April 19, 1974 - C.S. File 59/30

Douglas County Surveyors Office - R.B. Kimberling; M.W. Cline, crew - Oct. 27, 1977 - C.S. File 59/40-57

-----  
Found - A Fir stump 46" now 38", barked, bears N.26½°E., 47.5 ft. with well healed blaze. (O.B.T.)

28" now 30" Fir stump, bears S.8°E., 85.6 ft. (Rec. 89.8 ft. possible orig. BT)

I RESET corner from references set in 1974 by DCSO and attached those notes to my field notes in C.S. 59/40. References intersect within 0.07 ft.

Set a 5/8" x 30" Iron rod with 1½" alum. cap, set 9" below ground, marked: (Cont. Next Page)

TOWNSHIP 31 RANGE 03 POINT IDENTIFIER # 100500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 7 & 18; 12 & 13, T31-4

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Douglas Co. Surveyor

R	T 31 S	R
4	12   7	3
W	13   18	W

Set 3/4" x 30" bent iron pipe 21" in ground at edge of alum. cap, in a 24" mound of stone to top of I.P.

New Accessories:

30" Incense Cedar (used to reference cor. in 1974) bears N.73 3/4°W., 200.2 ft., double blazed and scribed "T31S R4W S12 CS BT"

12" D.Fir bears N.87°E., 92.4 ft., double blazed and scribed "T31S R3W S7 CS BT"

A 5/8" x 30" I.R. with 1 1/2" alum. set set 9" above ground mkd. "Douglas Co. B.O. Surveyor", bears N.35 3/4°W., 108.27 ft. (used to reference cor. in 1974)

Corner lies at end of road #31-4-13 in landing of a clear-cut unit.

BLM Dependent resurvey by A Bert Skeesick Cadastral Surveyor, and Robert H. Browning, Surveying Tech under Group No. 2300 surveyed Dec. 2004/Jan 2005 - (DCSO recs Vol. 56 Pgs 21973-4)

-----  
The cor. of secs. 7, 12, 13, and 18 on the E bdy. of the Tp., remonumented by Markham in 1959, further perpetuated & remonumented by the Douglas Co. Surveyors office in 1974 1977 respectively, monumented with an iron rebar, 5/8" dia., firmly set, buried 8" below surface of graveled road, with alum. cap (properly) mkd.

from which the remains of an orig. BT

A sawed decayed fir stump, 38" dia., bears N.28°E., 47.5 ft. with a healed blaze. (Rec. N.26 1/2°E.)

and accessories mkd. by the Douglas Co. Surveyors Office

A cedar, 34" dia., bears N.73 1/2°W., 200.4 ft. with a healed blaze.

A rebar, 5/8" dia., firmly set, projecting 8" above ground, bears N.35°46'21"W., 108.27 ft. with alum. cap mkd: DOUGLAS CO SURVEYOR B0.

and new BTs

A double topped cedar, 13" dia., bears N.40°E., 36.5 ft., mkd: T31S R3W S7 BT.

A fir, 12" dia., bears S.72 1/4°E., 22.6 ft. lks., mkd: T31S R3W S18 BT.

Corner is located in the middle of an overgrown graveled road

Fd. as per 2004 BLM resurvey - D.Edwards, 5/2010 - M160-63