

TOWNSHIP 31 RANGE 03 POINT IDENTIFIER # 100540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 7; & 12 of T31-4

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7796)

-----  
A Fir 8" dia., which I mark ¼ S on W. face, for ¼ sec. cor. from which

A Fir 14" dia., bears S.58°W., 18½ lks. dist. mkd. ¼ S BT.

A Fir 8" dia., bears N.19°W., 61 lks. dist. mkd. ¼ S BT.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. - Wit: R.G. Boyd - Nov. 1959-50

-----  
Determined by original BTs:

28" Fir N.19°E., 40.3 ft. I rescribed S7 T31S R3W BT.

At corner point, found 24" Fir mkd. ¼ S on West face.

Set 1½" x 48" Iron pipe, from which

6" Fir S.84°E., 42.0 ft. mkd. ¼ S7 R3W differential.

7" Fir S.75°E., 35.0 ft. mkd. ¼ S7 R3W BT.

12" Fir N.29°W., 31.0 ft. mkd. ¼ S12 BT.

Road bears South 290.0 ft.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady - Feb/March 1966 - C.S. File 54/20-37

-----  
Found - No trace of I P at corner as recorded by Markham.

28" D.Fir N.19°E., 40.3 ft., had been opened for scribe, "¼" on West face.

6" Fir, down, S.84°E., 42.0 ft.

7" D.Fir now 8", S.75°E., 35.0 ft., shows good scar.

12" now 13" D.Fir N.29°W., 31.0 ft. "BT" scribe visible.

Orig. corner tree had been opened for scribe "¼" on W. face.

Set brass cap at ¼ cor. mkd: County Surveyors Office

T 31 S  
R4W S 12 | S 7 R3W  
1966

As noted, road bears North 290.0 ft.

BLM retracement by A. Bert Skeesick Cadastral Surveyor & Robert Browning, Survey Technician, under Group #2100, surveyed Dec. 2004/Jan. 2005 - (DCSO rec Vol. 56 Pg 21974)

-----  
The ¼ sec. cor. of secs. 7 & 12, on the E bdy of the Tp., perpetuated by Markham in 1959, and by the Douglas Co. Surveyors Office in 1966, monumented with an iron post, 1¼" dia., firmly set projecting 3" above ground, in the remains of a decayed stump, size indeterminate, with brass cap properly mkd. continued next page

TOWNSHIP 31 RANGE 03 POINT IDENTIFIER # 100540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 7; & 12 of T31-4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the remains of an orig BT  
A sawed, decayed fir stump, 37" dia., bears N.20½°E., 42.2 ft. with no marks visible. (Record, N.19°W., 40.3 ft.)

and new BTs

A fir, 11" dia., bears N.32½°E., 29.9 ft., mkd: ¼ S7 BT.

A fir, 12" dia., bears N.41¼°W., 13.7 ft., mkd: ¼ S12 BT.

Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center.

The geodetic position (NAD 1983) of this corner as determined by a differentially corrected, C/A code GPS observation, is as follows:

Latitude: 42°53'31.3"N                      Longitude: 123°06'41.7"W

Fd. as per 2004 BLM resurvey - D.Edwards, 5/2010 - M160-63