

PRIMARY CORNER DESCRIPTION Sec Cor for 29, 30, 31 and 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 18 Page(s) 7692)

Set post, cor. to secs.29, 30, 31 and 32, from which
A Cedar 10" dia., bears N.48°E., 8 lks. dist.
A Fir 36" dia., bears S.35°E., 18 lks. dist.
A Cedar 12" dia., bears S.75°W., 8 lks. dist.
A Fir 14" dia., bears N.45°W., 7 lks. dist.

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7760)

The Sec. Cor., which is a post, 4" sq., firmly set, marked T31S S29 on NE.; R3W S32 on SE.; S31 on SW.; and S30 on NW. faces, with 5 notches on E. and 1 notch on S. edges; from which

A Fir 36" dia., bears S.35°E., 18 lks. dist. mkd. T31S R3W S32 BT.
A Cedar 12" dia., bears S.75°W., 8 lks. dist. mkd. T31S R3W S31 BT.
A Fir 4" dia., bears N.45°W., 7 lks. dist. mkd. T31S R3W S30 BT.

This tree is dead. The witness tree in sec. 29 is down, I mark 2 new trees as follows:

A Cedar 14" dia., bears N.67½°E., 26 lks. dist. mkd. T31S R3W S29 BT.
A Fir 16" dia., bears N.82½°W., 16 lks. dist. mkd. T31S R3W S30 BT.

George Wenderoth, Deputy Co. Surveyor - Probably 1946 or 1947 - M 27-14

Find all BTs in good shape.
Drive 1¼" Pipe for corner, from which
36" Fir bears S.35°E., 11.8 ft.
12" Cedar bears S.75°W., 5.2 ft.
14" Cedar bears N.67°30'E., 17.1 ft.
16" Fir bears N.82°30'W., 10.5 ft.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, crew - Jan. 1966 - C.S. File 52/63-52

Found - 1½" I.Pipe at sec. corner.
36" Fir now 46", S.35°E., 11.8 ft., shows good scar.
12" Cedar, down, S.75°W., 5.2 ft.

(Cont. Next Page)

TOWNSHIP 31 RANGE 03 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Sec Cor for 29, 30, 31 and 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

<p>14" Cedar now 26", N.67½°E., 17.1 ft., part of scribing visible. 16" Fir, windfall, N.82½°W., 10.5 ft., shows good scar. Set Brass cap alongside I.P. & mkd: County Surveyors Office T 31 S R 3 W S 30 S 29 S 31 S 32 1966 New BTs- 15" D.Fir S.87°W., 14.0 ft. scribed T31S R3W S31 CS BT. 13" D.Fir N.4°W., 82.0 ft. scribed T31S R3W S30 CS BT.</p>
<p>Fd. OK, DCSO, L. Monrean, deputy, Dec. 29, 1981 - CS 61/30-4 Fd. OK, Aug. 1991 by G. Nygren - M 114-7 Found OK by R. Wytcherley, Dec. 2003 - M143-63</p>
<p>Carl Sweeden - For: Roseburg Resources Co. - March 2012 - M163-35 ----- Found - 2½" DCSO 1966 BC, up 1.2' along side 1¼" ID pipe 12" Cedar BT S.75°W., 5.2', gone 50" D.Fir BT stump, S.35°E., 11.8' to face, scar vis. tag (2.0' tall) 16" D.Fir BT N.82½°W., (windfall per 1966 rec.) Gone 26" Cedar BT, N.67½°E., 17.1' to face, scar vis., tags (2) 20" D.Fir BT, S.87°W., 14.0' (to bole) scar vis., tagged 18" D.Fir BT, N.4°W., 82.0' (to bole) scar vis., tagged.</p>
<p>FD. Ok by R. Quimby, 3/2018 - C.S. 65/101-23</p>
<p> </p>