

TOWNSHIP 31 RANGE 03 POINT IDENTIFIER # 300140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 32 and 33

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 18 Page(s) 7691)

Set ¼ sec. post, from which
A W.Fir 10" dia., bears N.80°E., 40 lks. dist.
A Fir 16" dia., bears S.62°W., 28 lks. dist.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, crew - Feb. 1966 - C.S. File 52/63-87

Found - 10" W.Fir N.8°E., ~~16.4~~ 26.4* ft. Tree down and dead, found scribing "¼S BT"
No trace of SW. BT.

Set Brass cap at cor. mkd: County Surveyors Office
T 31 S R 3 W
¼ S32 | S33
1966

New BTs- 9" D.Fir S.39°W., 13.2 ft. scribed ¼ S32 CS BT.
14" D.Fir S.28°E., 17.1 ft. scribed ¼ S33 CS BT.
*corrected 2/16/2021

Dennis Gaylord, U.S.F.S. (Deputized by the DCSO) - Wit: Tony Flores - Sept. 20, 1979 - C.S. File 60/34-15

Found - Brass capped iron pipe set by the DCSO in 1966, is firmly set in place and mkd. County Surveyors Office T31S R3W ¼ S32 S33 1966. This brass cap was erroneously set. Record bearing from the original remaining BT is N.80°E. This 1966 brass cap was set S.8°W. from the BT.

A depression surrounded by Fir roots bears S.62°W., 18.48 ft. Nothing else remains of the SW BT.

A 14" D.Fir with double healed blazes which face the true corner location, bears S.39°E., 44.9 ft.

A 10" D.Fir bears S.21°E., 32.6 ft. and has double healed blazes. The blazes on this tree do not face the true corner location.

(The last two BTs were set by the County in 1966)

Set a 1" Iron pipe with a 2½" brass cap mkd. "County Surveyors Office T31S R3W ¼ S32 S33 1979", by reference from the above described original BT evidence. I remove all marks from 1966 brass cap and leave in place.

New BT - A 13" D.Fir bears N.7°W., 10.7 ft. scribed "¼ S32 CS BT" on double blazes.

Fd. OK, Aug. 1991 by G. Nygren - M 114-7