

PRIMARY CORNER DESCRIPTION Sec Cor for 28, 29, 32 and 33

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 18 Page(s) 7691)

Set post in dry gulch, cor. to secs.28, 29, 32 and 33, from which

- A Fir 16" dia., bears N.50°E., 37 lks. dist.
- A Fir 16" dia., bears s.60°E., 51 lks. dist.
- A Fir 10" dia., bears S.30°W., 22 lks. dist.
- A Fir 14" dia., bears N.50°W., 35 lks. dist.

Fd. and Used in GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7748)

C.E. Roberts - Sept. 20, 1909 - Field Book 10 Pg. 51

Put in N.W. Corner of 33. Old BTs badly decayed.
Marked C.S.

- A Fir 12" dia., S.76 3/4°E., 31 lks.
- A Fir 12" dia., S.32½°W., 59 lks.

DCSO, 1960, C.S. File 52/63-2 - "Do not believe Roberts renewed sec. cor. Do not find his BTs. but find all orig. BTs. See following corner visit."

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; Clete Putnam, crew - Dec. 22, 1960 - C.S. 52/63-1

Found - Orig. 16" now 40" Fir, bears S.60°E., 33.7 ft. Shows good scar.
Orig. 10" now 14" Fir, S.30°W., 14.5 ft., shows good scribing "31".
Orig. 16" now 24" Fir snag shell only, N.50°E., 24.4 ft., shows old scar.

Set Brass cap at cor. mkd: County Surveyors Office

T 31 S R 3 W
S 29 | S 28
S 32 | S 33
1960

- New BTs- 19" R.Fir bears N.85°E., 24.8 ft. scribed S28 T31S
R3W CS BT.
17" R.Fir bears N.54°W., 27.7 ft. scribed S29 T31S
R3W CS BT.
14" R.Fir bears S.3°E., 13.6 ft. scribed S33 T31S
R3W CS BT.

(Cont. Next Page)

TOWNSHIP 31 RANGE 03 POINT IDENTIFIER # 300200

PRIMARY CORNER DESCRIPTION Sec Cor for 28, 29, 32 and 33

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike Stone & Wm. Stoffel & M. Stone, crew - May 1964 - C.S. File 52/63-7

Found - DCSO brass cap set in 1960.
14" D.Fir S.30°W., 14.5 ft., scribing visible.
14" D.Fir S.3°E., 13.6 ft., scribing visible.
All other bearing trees, both renewals and originals, are now uprooted and down.
New BTs- 12" D.Fir N.71°W., 47.3 ft. mkd. T31S R3W S29 CSBT
11" D.Fir N.25°E., 32.7 ft. mkd. T31S R3W S28 CSBT
Corner lies in bottom of small draw.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, crew - Jan/Feb. 1966 - C.S. File 52/63-79

Found - 14" D.Fir S.30°W., 14.5 ft., shows good scar, pitched over.
14" D.Fir S.3°W., 13.6 ft., shows good scar, pitched over.
12" D.Fir N.71°W., 47.3 ft., scribe visible "R3W S29 BT"
11" D.Fir N.25°E., 32.7 ft., scribe visible "T31S R3W S28 CS BT"
No trace of DCSO brass cap set in 1960.
Set Brass cap at cor. mkd: County Surveyors Office
T 31 S R 3 W
S 29 | S 28
S 32 | S 33
1966

All bearing trees in good condition.

Fd. OK, Aug. 1991 by G. Nygren - M 114-7

Fd. and Used in BLM Resurvey by Boyd W. Peterson and Dale T. Bedell, Cadastral Surveyors, Under Group #'s 1277 & 1315, Surveyed Sept. 1985/August 1986 - (DCSO records Vol. 48 Page(s) 18327)

Found OK by R. Wytcherley, Dec. 2003 - M143-63