

TOWNSHIP 31 RANGE 03 POINT IDENTIFIER # 340200

PRIMARY CORNER DESCRIPTION N. 1/4 Cor. for Sec. 33 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 18 Page(s) 7691-92)

Set ¼ sec. post, from which
A Laurel 5" dia., bears N.20°W., 24 lks. dist.
A Pine 12" dia., bears S.30°E., 22 lks. dist.

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7747)

The ¼ sec. cor., which is a post, greatly decayed, marked ¼ S on N. face, I find the 2 witness trees. I remove this post cor. and set a stone 15x10x5 ins., 10" in the ground, for ¼ sec. cor. marked ¼ on N. face; from which
A Pine 12" dia., bears S.30°E., 22 lks. dist. mkd. ¼ S BT.
A Laurel 5" dia., bears N.20°W., 24 lks. dist. mkd. ¼ S BT. This tree is dead. In its stead, I mark a:
Fir 22" dia., which bears N.47½°E., 72 lks. dist. ¼ S BT.

C.E. Roberts - Sept. 20, 1909 - Field Book 10 Pg. 51

Set ¼ sec. corner on North Bdy of section 33 as per original certified notes. Only one BT and it is cut off and destroyed. I put in two new BTs. in Section 28. No other trees in 33.
A W.Fir 32" bears N.20°15'W., 168 lks.
A Red Fir 30" dia., bears N.15°15'E., 144½ lks.

Searched for, not fd by DCSO J.M.P., Feb. 1966 C.S. 54/20-37A

Survey by William Ruppert, LS #866 - For: U.S. Forest Service March 1980 - M 79-29

Found - 38" D.Fir stump bears N.47°30'E., 47.5 ft. "¼" visible scribe on face.
Set 2" x 30" alum. pipe with 2½" magnetized cap marked T31S R3W ¼ S33 PLS 866 1980.
New BTs- 18" D.Fir bears S.14°43'E., 75.4 ft., scribed "¼ S33 BT".
7" D.Fir bears S.46°00'W., 8.3 ft. scribed "¼ S33 BT".
This corner re-established from original bearing tree set in 1894 by Wm. Bushey.

(Cont. Next Page)

TOWNSHIP 31 RANGE 03 POINT IDENTIFIER # 340200

PRIMARY CORNER DESCRIPTION N. 1/4 Cor. for Sec. 33 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Fd. and Used in BLM Resurvey by Boyd W. Peterson and Dale T. Bedell, Cadastral Surveyors, Under Group #'s 1277 & 1315, Surveyed Sept. 1985/August 1986 - (DCSO records Vol. 48 Page(s) 18326)

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and Jeff Lorsung - 7/21/2025 - C.S. File 67/60-58

Found - 2½" Alum cap.

T31S R3W
ONLY
¼

S33
PLS 866
1980

Very rotted 32"x2½' D.Fir stump N.47°30'E. 47.5 ft
21"x8 ft sawn Fir stump S.17°43'E. 75.4 ft.
19" D.Fir S.46°W. 8.2 ft.

New - Carsonite post with National Forest sign east 3.8 ft
14" D.Fir S.77½°E. 7.7 ft. Fully healed double
blaze marked by persons unknown in 2009
(Initials LPG) on tag.

Notes - Mon is approx 250' S.W. of logging landing on old
E-W cut line.

Compass decl. 14¼°E.
OCS COORDINATE SYSTEM
COTTAGE GROVE-CANYONVILLE ZONE
42°50'30.73779" N
123°03'43.73235 W.