

PRIMARY CORNER DESCRIPTION Sec Cor for 3, 4, 9 and 10

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7744)

-----  
Set a stone 14x10x6 ins., 10" in the ground for cor. to secs. 3, 4, 9 and 10, marked with 3 notches on E. and 5 notches on S. edges; from which

A Fir 48" dia., bears N.27¼°E., 62½ lks. dist. mkd. T31S R3W S3 BT.

A Fir 13" dia., bears S.24°E., 22 lks. dist. mkd. T31S R3W S10 BT.

A Fir 20" dia., bears S.65½°W., 19½ lks. dist. mkd. T31S R3W S9 BT.

A Fir 10" dia., bears N.49°W., 38 lks. dist. mkd. T31S R3W S4 BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike Stone & Wm. Stoffel - July 20, 1964 - C.S. File 52/63-12

-----  
Found - Stone as called for in govt. notes.  
18" Fir snag, S.24°E., 14.5 ft., previously opened, good scribing visible "R3W".  
38" Fir S.65½°W., 12.9 ft., shows good lower scar. Tree in good condition.  
12" Fir N.49°W., 25.1 ft., slope dist., very plain scars visible, good condition.  
The 48" Fir N.27¼°E., 41.2 ft., uprooted and down, scars visible.

Set Brass cap at cor. mkd: County Surveyors Office  
T 31 S R 3 W  
S 4 | S 3  
S 9 | S 10  
1964

New BTs- 15" I.Cedar S.14°E., 37.2 ft. mkd. T31S R3W S10 CS BT.

36" D.Fir N.22°E., 56.8 ft. mkd. T31S R3W S3 CS BT.

BLM resurvey by John Jelley, Cadastral Surveyor, Group #555, surveyed July/Aug 1964 - (DCSO records Vol. 33 Page(s) 13830)

-----  
The Sec. cor., monumented with the original basalt stone, 14x10x6 ins., firmly set, 5" in the ground, mkd. with 5 notches on S. and 3 notches on E. edge, recorded and remonumented by Godfrey in 1964, with an iron pipe 1" dia., 12" above the ground, firmly set, with the corner stone alongside and a brass cap mkd. in 1964 from which the original bearing trees  
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec Cor for 3, 4, 9 and 10

Alias	Description
Alias	Description
Alias	Description
Alias	Description

A down and rotted Fir 48" dia., bears N.27¼°E., 62½ lks. dist., with a healed blaze.  
A dead Fir 20" dia., bears S.24°E., 22 lks. dist., with scribe marks R3W visible on opened blaze.  
A Fir 40" dia., bears S.65½°W., 19½ lks. dist., with a healed blaze.  
A Fir 13" dia., bears N.49°W., 36½ lks. dist., with a healed blaze.  
and bearing trees mkd. by Godfrey:  
A Fir 37" dia., bears N.22°E., 86 lks. dist., with scribe marks T31S R3W S3 CS BT visible on new blaze.  
A Cedar 15" dia., bears S.14°E., 56 lks. dist., with scribe marks T31S R3W S10 CS BT visible on new blaze.  
Add marks BLM 1964 to bottom of brass cap.

BLM Dependent resurvey, rehabilitation, & remonumentation by A. Bert Skeesick, Cadastral Surveyor, and Robert H. Browning, Surveying Tech., under Group No. 2000, 2100, 2300 - Surveyed Aug. 2005/Feb. 2006 - (DCSO records Vol. 55 Page 21618 & 2009 BLM Plat)

-----

The cor. of secs. 3, 4, 9, & 10 monumented with the orig. basalt stone, 10x6x2" showing above ground, with faint notches visible on SW edge, with an iron post, 1¼" dia., firmly set alongside the orig. stone, projecting 8" above ground, with brass cap mkd as reported by Jelley in 1964; from which the remains of the orig. BTs  
A sawed, decayed fir stump, 30". dia., bears S.65½°W., 12.9 ft., with no marks visible.  
A sawed, decayed fir stump. 20" dia., bears N.49°W., 24.1 ft., with no marks visible.  
and the remains of BTs reported by Jelley  
A fir snag. 37" dia.. bears N.22°E., 56.8 ft., with no marks visible.  
A sawed, burnt cedar stump, 20" dia. bears S.14°E., 37.0 ft., with a healed blaze.  
and new BTs  
A fir, 5" dia., bears N.88°E., 16.0 ft., mkd: X BT.  
A fir, 4" dia., bears S.42½°E., 13.8 ft., mkd: X BT.  
A fir, 5" dia., bears S.22¼°W., 15.0 ft., mkd: X BT.  
A fir, 6" dia., bears N.7½°W., 6.9 ft. mkd: T31S R3W S4 BT