

TOWNSHIP 31 RANGE 03 POINT IDENTIFIER # 500500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 10, 11, 14 and 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7727)

Set a stone 12x10x6 ins., 8" in the ground for cor. to secs. 10, 11, 14 and 15, marked with 2 notches on E. and 4 notches on S. edges; from which

A Laurel 14" dia., bears N.49½°E., 47½ lks. dist. mkd. T31S R3W S11 BT.

A Fir 32" dia., bears S.41°E., 58 lks. dist. mkd. T31S R3W S14 BT.

A Fir 28" dia., bears S.33¾°W., 22 lks. dist. mkd. T31S R3W S15 BT.

A Fir 33" dia., bears N.59½°W., 9 3/4 lks. dist. mkd. T31S R3W S10 BT.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. - Wit: O.A. Keatley - Nov. 18, 1959 - C.S. File 42/392-40

Determined by O.B.T.s:

40" Fir S.41°E., 38.3 ft., found scribe.

36" Fir snag, N.60°W., 6.6 ft.

16" Laurel N.49°E., 31.4 ft., I rescribe "S11 BT".

At corner point found stone and Set 1/2" x 24" Iron pipe, from which

4" Pine S.5°E., 21.6 ft. "S14 BT".

5" Live Oak S.37°E., 28.0 ft. "S14 BT".

4" Chinquapin S.86°W., 10.1 ft. "S15 BT".

13" Laurel N.15°E., 5.6 ft. "S11 BT".

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike Stone Wm. Stoffel, Mike Darby, crew - June 1964 - C.S. File 52/63-10

Found - 3/4" Iron pipe set by Markham.

40" D.Fir S.41°E., 38.3 ft. Some scribing visible through pitched over face.

18" Laurel N.49°E., 31.4 ft. Shows faint scars.

The Fir tree, S.33½°W., 14.5 ft. is uprooted and down. Good scar visible.

The Fir, N.59½°W., 6.5 ft. is down and badly rotted. Axe marks found, but no scribing.

All trees marked by Markham in good condition as follows:

4" Pine S.5°E., 21.6 ft.

5" Live Oak S.37°E., 28.0 ft.

4" Chinquapin S.86°W., 10.1 ft.

13" Laurel N.15°E., 5.6 ft. (No scribing on upper blaze, "BT" bark scribed) (Cont. Next Page)

TOWNSHIP 31 RANGE 03 POINT IDENTIFIER # 500500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 10, 11, 14 and 15

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Set Brass cap at cor. mkd: County Surveyors Office
T 31 S R 3 W
S 10 | S 11
S 15 | S 14
1964

Reset Iron pipe alongside.
Reblaze and scribe:
13" Laurel N.15°E., 5.6 ft. mkd. "T31S R3W S11 CS
BT".
Corner lies on steep West slope.

BLM resurvey by John Jelley, Cadastral Surveyor, Group #555,
surveyed July/Aug 1964 - (DCSO records Vol. 33 Page(s) 13824-
25)

The sec. cor. recorded and remonumented by Markham in 1959,
with an iron pipe, 3/4" dia., 4" above the ground, firmly
set, subsequently remonumented by Godfrey in 1964 with an
iron pipe, 1" dia., 12" above the ground, firmly set, with
1964 brass cap attached
from which the original bearing trees:

A Madrone 14" dia., bears N.49½°E., 48½ lks. dist., with
scribe marks S11 R3W BT and other illegible marks
visible on bark blaze. (Rec. dist., 47½ lks.)

A Fir 40" dia., bears S41°E., 58 lks. dist., with
illegible scribe marks visible on opened blaze.

A down Fir 24" dia., bears S.33¼°W., 22 lks. dist., with
healed double blaze.

A shell of a Fir stump 36" dia., bears N.39½°W., 9 3/4
lks. dist.

and bearing trees marked by Markham:

A Madrone 11" dia., bears N.15°E., 8½ lks. dist. with
scribe marks T31S R3W S11 CS BT visible on new blaze.
(Was remarked by Godfrey in 1964)

A Live Oak 6" dia., bears S.37°E., 42½ lks. dist. with
scribe marks S BT visible on partially healed double
blaze.

A Pine 6" dia., bears S.5°E., 33½ lks. dist. with scribe
marks S BT visible on partially healed double blaze.

A Chinquapin 5" dia., bears S.86°W., 16 lks. dist. with
scribe marks S15 BT visible on partially healed double
blaze.

and a new bearing tree:

A Fir 7" dia., bears N.48°W., 91½ lks. dist. mkd. T31S R3W
S10 BT.

Add marks BLM 1964 to bottom of brass cap.

continued next page

TOWNSHIP 31 RANGE 03 POINT IDENTIFIER # 500500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 10, 11, 14 and 15

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Ron Quimby - Crew: N. Fromdahl & R. Olson - 9/2015 - C.S.
File 65/89-36

Found - DCS0 brass cap (properly mkd)
Madrone stob N.49½°E., 32.0 ft. - badly burnt.
10" live oak S.37°E., 28.0 ft. - good scar.
12" pine S.5°E., 22.1' ft. - good scar.
10" chinquapin S.86°W., 10.6 ft. - good scar.
7" Down fir (N.48°W., 60.4 ft. rec.) - badly burnt.
New - 5/8" I.Rod S.47°W., 15.0 ft.
5/8" I.Rod S.30°E., 15.0 ft.
5/8" I.Rod N.44°E., 15.0 ft.
5/8" I.Rod N.48°W., 10.0 ft.

All rods have yellow plastic caps stamped ie engineering
Note - Area badly burnt 8/2015
Compass decl. 15½°E.