

TOWNSHIP 31 RANGE 03 POINT IDENTIFIER # 500640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 2 and 3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7732)

-----  
Set a stone 14x12x5 ins., 9" in the ground, for 1/4 sec. cor. marked 1/4 on W. face; from which

A Fir 7" dia., bears S.38 3/4°E., 16 3/4 lks. dist. mkd. 1/4 S BT.

A Yew 6' dia., bears N.25°W., 5 1/2 lks. dist. mkd. 1/4 S BT.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. - Wit: R.G. Boyd - Dec. 16, 1958 - C.S. File 42/392-8

-----  
Determined by O.B.T.s:

6" yew, dead snag, bears N.25°W., 3.6 ft., found scribe.

14" Fir bears S.39°E., 10.1 ft., found scribe.

At corner point found stone mkd. 1/4, from which

15" Fir bears N.31°E., 68.0 ft. on slope, mkd. 1/4 S2 BT on bark.

25" Alder bears S.57°W., 137.0 ft. on slope, mkd. 1/4 S3 T31S R3W BT.

30" Hemlock bears S.75°W., 163.0 ft. on slope, mkd. 1/4 S3 BT.

Stouts Creek bears South 145.0 ft.

The logging road will be built through 1/4 corner, that is why I picked new trees at such distance.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike Stone, Mike Darby & Wm. Stoffel, crew - June 1964 - C.S. File 52/63-9

-----  
Found - 30" Hemlock S.75°W., 163.0 ft. (Slope dist. according to Markham), uprooted and down. Scribing visible "1/4 S3".

25" Alder S.57°W., 137.0 ft., dead, leaning badly and blazes buried in sand, rock and debris.

15" Fir with scribing, lying alongside of road. Could not tell where it had stood.

Corner falls in logging road near cut bank on North side.

Drove 3/4" Iron rod in road at corner.

New BTs- 36" D.Fir N.66°W., 181.0 ft. mkd. 1/4 S3 CS BT.

10" D.Fir N.62°W., 411.9 ft. mkd. 1/4 S3 CS BT.

No trees near East of line. Location impracticable to set a witness corner.

Fd. OK, by DCSO, J.Powell - Dec. 1965 C.S. File 52/63-39

(Cont. Next Page)

TOWNSHIP 31 RANGE 03 POINT IDENTIFIER # 500640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 2 and 3

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Douglas Co. Surveyors Office - R.B. Kimberling; M.W. Cline;  
S.J. Flause, crew - Oct. 25, 1977 - C.S. File 59/40-55

-----  
Found - A 3/4" Iron rod, bent over.  
A 10" now 12" D.Fir bears N.62°W., 411.9 ft. with  
partially healed, barked, double blaze and  
visible scribing "CS BT"  
Set a 5/8" x 30" Iron rod with 1 1/2" alum. cap, set 1.0 ft.  
below road surface elevation, mkd. "Douglas Co. 1/4 S3 S2  
1977 Surveyor".  
New BT - A 6" Maple bears S.29°W., 28.6 ft. double blazed and  
scribed "1/4 S3 CS BT"  
Corner is in ditch of existing road.

James Klein - Keith Primm - Douglas Popham - For:  
Williams/Pacific Connector Pipeline - 5/2015 - M166-40 A-I &  
M171-2 A-D

-----  
Searched for not found.

Greg Lang - 1/14/2016 - C.S. File 65/95-11

-----  
Found - 5/8" iron rod with alum. cap in road ditch. Set by  
Douglas Co. survey crew in 1977  
25" D.Fir stump bears N.62°W., 412.34 ft. (scribed  
by Douglas Co. in 1964)\*  
12" Broken maple bears S.29°W., 29.50 ft. (scribed  
by Douglas Co. in 1977)\*  
New - Set steel post at corner.  
18" D.Fir stump with nail in top bears S.84°E.,  
29.50 ft.  
10" D.Fir bears S.22°E., 59.40 ft. scribed "1/4 S2 BT"  
Note - \*Set nail in the top of the existing 25" D.Fir stump  
which bears N.62°W., 412.34 ft; also set nail in  
the top of the broken 12" Maple which bears  
S.29°E., 29.50 ft.  
Corner is in the ditch of an existing rock logging road.