

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 35 only, T30-3

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 16 Page(s) 6776)

-----  
A Hemlock 5" dia., which I mark ¼ S on N. face, for ¼ sec. cor., from which

A Fir 22" dia., bears S.62½°W., 23 lks. dist. mkd. ¼ S BT.

A Fir 30" dia., bears N.79¼°W., 38 lks. dist. mkd. ¼ S BT.

Survey by Richard L. Templin, Jr. - For: Oregon Conference of Seventh Day Adventists - Oct. 1, 1953 - C.S. File 41/196

-----  
From the ¼ cor. betw. secs. 26 & 35, I run due South and fall 27.9 ft. West of the South ¼ cor. which is an 8" Hemlock mkd. "¼S" on North face, said cor. being 4650.0 ft. South of the North ¼ corner of sec. 35. As none of bearing trees are left at the S. ¼ corner of sec. 35, I scribe the following trees:

28" Cedar S.33°E., 37.2 ft. mkd. ¼ S2 BT RE 3024.

18" Hemlock N.30°W., 40.1 ft. mkd. ¼ S35 BT.

I also set a 1½" Iron pipe as a witness corner 1.0 ft. North of the true corner, mkd. "WC" on N. face and "RE 3024" on South face.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, crew - Dec. 1965 - C.S. File 52/63-29

-----  
Found - 1" I.Pipe, 1.0 ft. N. of ¼ corner.

28" Cedar stump, S.33°E., 37.2 ft. (bearing should be S.30°E.)

18" now 19" Hemlock N.30°W., 40.1 ft. (bearing should be N.33°W.), shows good scar and pitched over scribe.

Corner tree is stump.

Set Brass cap at cor. mkd: County Surveyors Office

T 30 S R 3 W

¼ S 35

T 31 S R 3 W

1965

New BT - 5" Hemlock N.57°E., 24.2 ft. scribed ¼ S35 CS BT.

Douglas Co. Surveyors Office - Larry E. Monrean, Deputy - Wit: J.M. Powell - July 11, 1983 - C.S. File 62/9-21

-----  
Found - Orig. Hemlock corner tree, is down and rotted. Remains of trunk show signs of a healed blaze. No scribing visible. Also found a 1952 location poster on decayed trunk.

(Cont. Next Page)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

From the center of the decayed stump, found a 1½" dia, iron pipe, bears N.15°E., 1.0 ft. (1953)  
Found 1" iron pipe with brass cap set by Powell, is along northerly side of iron pipe. (1965)  
28" Cedar now a decayed stump with scribing "S2 BTRE" visible bears S.29°E., 37.9 ft. from 1½" I.P. (Rec. S33°E., 37.2 ft., 1953 and S.30°E., 1965)  
18" Hemlock now 20" with healed blaze, bears N.28°W., 40.0 ft. (Rec. N.30°W., 40.1 ft. and N.33°W.) from the 1½" iron pipe.  
5" Hemlock now 9" with well healed blaze bears N.58°E., 24.0 ft. (Rec. N.57°E., 24.2 ft.) from the 1½" Iron pipe.  
As the iron pipe (1½" dia.) from 1953 is firmly set, I leave it in position for the witness corner. I remove the found 1" dia. x 36" Iron pipe with attached brass cap. As this monument is in good condition, I SET it in the true corner position and add the following "RESET 1983".  
New BTs- 6" D.Fir double blazed and scribed "S2 CS BT" bears S.37°E., 10.2 ft.  
8" D.Fir double blazed and scribed "S2 CS BT" bears S.23½°W., 13.9 ft.  
New Bearings and distances to BTs from previous renewals:  
20" Hemlock bears N.26½°W., 40.8 ft.  
9" Hemlock bears N.56½°E., 24.7 ft.  
Corner lies in E-W cutting ling (timber to the North) approx. 400 ft. West of road.

Fd. and Used in BLM BLM resurvey by Wayne L. Rogers; Lance J. Bishop; James L. White, Cadastral Surveyors, under Group #1133 - Surveyed June 7, 1983/Dec. 12, 1984 - (DCSO records Vol. 47 Page(s) 17846-47)

James Klein & Richard Kitz - For: Pacific Connector Gas Pipeline Project/Williams - Sept. 2014 - M166-19 A-E; revised by M166-45 A-E

-----  
Found - 2½" brass cap stamped County Surveyors Office 1965  
reset 1983  
BTs - 19.3" Hemlock with healed face and tag dated 7/83;  
N.56½°E., 24.7' to nail side center  
19.5" D.Fir with healed face set tag dated 10/13;  
S.23½°W., 13.9' to nail side center