

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 16 Page(s) 6774-75) and (duplicate pg. 6907, Vol. 16)

The West bdy. of Sec. 31, is reported to be 75.15 chs. long. As this closing is not within the 3 chain limit, I therefore set a closing cor. at this point of intersection which is Fir post, 5 ft. long, 4" sq., 24" in the ground for closing cor. to township 30 South Range 2 and 3 West, marked C C T30S on N.; R2W S31 on E.; and R3W S36 on W. faces with 6 notches on NE and W. faces, from which
A Fir 26" dia. bears N.59½°E., 102 lks mkd T30S R2W S31 BT
A Cedar 30" dia bears N.16¼°W. 73½ lks mkd T30S R3W S36 BT
A Fir 29" dia., bears S.82½°E., 37 lks mkd T30S R's 2 & 3 W, C C BT.

Douglas Co. Surveyors Office - A. Victor Cangie; Jim Cook; Mike Tompkins - Sept. 14, 1976 - C.S. File 59/24-12

Found - Orig. 26" now 36" Fir that bears N.59½°E., 64.5 ft. (Rec. 67.3 ft.) Alive and well. Shows good scar.
Orig. 30" now 36" Cedar bears N.16¼°W., 48.5 ft. Tree is alive and shows good scar.
Orig. 29" now 31" stump that bears S.82½°E., 24.4 ft. Visible scribing showing.

Set a 1"x30" Iron pipe with brass cap stamped:

Douglas Co. Surveyor

T 30 S	
R 3 W	R 2 W
S 36	S 31

Closing
Corner
1976

New BT - 12" Hemlock bears N.80°E., 34.3 ft. mkd. "T30S R2W S31 CS BT" in a double blaze.

Ron Quimby - Crew: N. Fromdahl & L. Heddens - 6/2020 - C.S. File 65/106-33

Found - DCSO brass cap (properly mkd)
38"x4' capped Fir stump N.59½°E., 64.5 ft. good scar
37"x6' Cedar stump N.16¼°W., 48.5 ft.
Rotten log remnant & roothole tin cap on ground N.80°E., 34.3 ft
New - 9" Fir N.56°E., 16.3 ft. scribed T30S R2W S31 CC BT
7" Fir N.35°E., 12.3 ft. scribed T30S R2W S31 CC BT
10" Fir N.9°W., 43.5 ft. scribed T30S R3W S36 CC BT
11" Fir N.4°W., 11.3 ft. scribed T30S R3W S36 CC BT
Note - Compass decl. 15½°E.