

PRIMARY CORNER DESCRIPTION NW Cor. Sec. 6, T31-2 (On E. bdy. S. 1)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Fred Mensch , Deputy Surveyor - under Contract #766, dated May 10, 1906 (DCSO records Vol. 18 Page(s) 7668 3/4)

Set a Madrone post, 3 ft. long, 4" sq., 24" in the ground, for closing cor. to Tps. 30 and 31 S., R. 2 W., marked: T30S S31 on N.; C C R2W on E.; and T31S S6 on S. faces, with 6 grooves on E. and S. faces, from which

A Fir 24" dia., bears N.52½°E., 32 lks. dist. mkd. T30S R2W S31 BT.

A Madrone 6" dia., bears S.52°E., 42 lks. dist. mkd. T31S R2W S6 BT.

Destroy marks on former cor. and bearing trees referring to T31S R2W.

For Roseburg Lumber Co. by F. McCornack; Welker; Ohman and Carstenson - May 24, 1955 (Info. filed Dec. 1, 1981) - C.S. File 58/188-3

Found - Post obliterated.
Scribing plainly visible, Laurel 15", S.52°E., 27.7 ft.
Evidence of Fir stump, N.52½°E., 19.8 ft.
Metal tag, N.20°W., 8 ft.

Douglas Co. Surveyors Office - Gregory Quibell, Deputy - Teresa Buley, crew - Nov. 23, 1981 - C.S. File 61/29-32

Found - 2" x 2" Fir post, 24" long, with nail in top, lying in approx. vicinity of corner. (Probably from Roseburg Lbr. survey)

Original Post gone.
Probable remains of orig. 24" Fir now 28" rotted stump, flush with ground.
Metal tag nailed on slab of bark lying at base of rotted 40" Fir snag approx. 3 ft. tall, per Rsbg. Lbr. Co. survey.

I could not find any sign of original 6" Madrone which was seen in 1955 with scribing visible. Several small Madrones are growing in the vicinity of orig. Madrone BT, but I do not feel any of them are the BT.

Using the 24" Fir stump I believe to be the orig. Fir BT and using brg. and dist. mentioned in the 1955 Rsbg. Lbr. survey (S.52½°W., 19.8 ft.) (Orig. 21.1 ft.) I SET a 1" x 30" I.P. with brass cap attached mkd: Douglas Co. Surveyor CC S31 S6 T30S T31S R2W 1981.

(Cont. Next Page)

TOWNSHIP 31 RANGE 03 POINT IDENTIFIER # 700674

PRIMARY CORNER DESCRIPTION NW Cor. Sec. 6, T31-2 (On E. bdy S.1)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Metal tag and tree per Rsbg. Lbr. survey was used only as a rough check. Record stated N.20°W., 8 ft. I find center of tree 8 ft., face of tree 6.2 ft. and bearing to center of base of tree, N.2°W. The way the tree seemed to be leaning when alive, could have had a bearing of N.20°W., to the tag itself if it were about 6 ft. high.

New BTs- 13" Fir scribed "T30S R2W S31 CS BT" in double blaze bears N.10°E., 21.4 ft.

11" Fir scribed "T30S R2W S31 CS BT" in double blaze bears N.26°E., 29.8 ft.

9" Chinquapin scribed "T31S R2W S6 CS BT" in double blaze bears S.89°E., 26.4 ft.

10" Chinquapin scribed "T31S R2W S6 CS BT" in double blaze bears S.16°E., 11.7 ft.

Corner location fell on line with a very well blazed N-S line.

(Sketch in C.S. File 61/29)

Ron Quimby - For: Roseburg Resources Co - Dec. 2014 - M166-27

Found - Brass cap per 1981 DCSO Renewal

13" Fir N.10°E., 21.4' healed face

11" Fir N.26°E., 29.8' healed face

BOTH HAVE CORRECT DISTANCE WRITTEN ON TAGS, BUT WRONG BEARINGS

9" Chinquapin S.89°E., 26.4' healed face

FELL OVER AND LEANING ON ANOTHER TREE

11" Chinquapin S.16°E., 11.7' healed face