

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 140400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 18 and 19

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7862)

A Fir 6" dia., which I mark 1/4 S on N. face for 1/4 sec.cor, from which
A Fir 11" dia., bears S.19 1/4°W., 10 lks. dist. mkd. 1/4 S BT.
A Fir 14" dia., bears N.34°W., 16 3/4 lks. dist., mkd. 1/4 S BT.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. - Wit: J.R. Markham; R.G. Boyd - Oct. 7, 1959 - C.S. File 42/391-39

Determined by O.B.T.s:
11" Fir S.19°W., 6.6 ft.
16" Fir N.34°W., 11.0 ft.
At corner point, found 6" Fir, dead and down, scribed 1/4S on N. face, and SET 1/2" x 40" Iron rod, from which
8" Cedar bears N.87°W., 35.0 ft. mkd. 1/4 S19 BT.
14" Laurel bears S.46°W., 19.0 ft. mkd. 1/4 S19 BT.
8" Cedar bears N.68°E., 22.0 ft. mkd. 1/4 S18 BT.
Road and top of main ridge bears North, 200.0 ft.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, crew - Feb. 1966 - C.S. File 54/20-20

Found - Iron rod out of the ground.
Orig. 16" Fir, down, N.34°W., 11.0 ft.
Orig. 11" Fir, dead, S.19°W., 6.6 ft., shows good scar.
8" Cedar N.87°W., 35.0 ft., gone
14" Laurel S.46°W., 19.0 ft. gone.
Set Brass cap at cor. mkd: County Surveyors Office
T 31 S R 4 W
1/4 S 18
S 19
1966

Set Iron rod alongside.
New BT - 40" D.Fir, West 80.0 ft. scribed 1/4 S19 CS BT.

(Corner referenced out Jan. 30, 1978 for road construction)

Douglas County Surveyors Office - Larry E. Monrean, Deputy - T. Plouff, witness - March 30, 1981 - C.S. File 61/19-19

Not Found:
Original corner tree monument not found.
(Cont. Next Page)

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 140400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 18 and 19

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Not Fd.- 1/2" x 40" I.R. not found.
Found - A 1" x 36" I.P. with brass cap stamped "County Surveyor Office T31S R4W 1/4 S18 S19 1966". Cap had been removed from corner position and placed at a position safe from road construction. As road construction has been completed:
We set a temporary marker at position of 1/4 corner by using references as noted in 1978 corner reference notes (removed from C.S. File 59/30 and attached to these field notes.)
Found - Orig. 14" Fir N.34°W., 11.0 ft. is down, has partially healed double blaze.
Orig. SW. BT not found.
A Cedar 8" now 14", with partially healed double blaze, bears N.68°E., 22.0 ft. (brg. OK to face). Base of tree bears N.72½°E., 22.0 ft.
No other trees found from 1959 renewal.
A D.Fir 40" bears N.88°W., 78.3 ft. (Rec. West, 80.0 ft.) Tree has well healed double blaze.
As the corner position now falls on N. cutbank of road, we build stone wall around base of corner position, 5½ ft. long, 3 ft. high. Also the bank above corner is terraced and rocks set in to stop erosion. SET found brass cap at corner position and stamp "Reset 1981".
New BTs- 8" I.Cedar bears N.40°W., 17.8 ft. double blazed, scribed "1/4 S18 CS BT"
11" D.Fir bears N.1½°E., 39.8 ft., double blazed, scribed "1/4 S18 CS BT".
12" I.Cedar bears S.61½°E., 117.9 ft., double blazed, scribed "1/4 S19 CS BT".
No other trees available in sec. 19 for scribing.

Bruce Shaner - For: Seneca Jones Timber Co. - March 2002 - M139-61 & C.S. File 65/42-40B

Found - DCS0 2½" brass cap in large mound of stone.
24" Cedar BT, face overgrown, bears N.68°E., 22. ft.
14" Cedar BT, face overgrown, bears N.40°W. 17.8 ft.
22" D.Fir BT, high stump only, bears N.6°E., (Rec. N.1½°E.) 39.8 ft.
12" Cedar BT, scribes "BT" visible now only a stump, bears S.61½°E., 117.9 ft.
6 ft. steel fence post bears West, 1.0 ft.
New BT - 22" D.Fir BT, I scribed "1/4 S19 BT" bears S.35°E., 78.5 ft.

Fd. Ok by K. DeGroot, 3/2005 - M 146-19