

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 200140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 31 and 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7849)

A Fir 8" dia., which I mark $\frac{1}{4}$ S on W. face, for $\frac{1}{4}$ sec. cor., from which

A Fir 30" dia., bears N.33 $\frac{1}{2}$ °W., 38 lks. dist. mkd. $\frac{1}{4}$ S BT.

A Fir 30" dia., bears N.35 $\frac{1}{4}$ °E., 40 lks. dist. mkd. $\frac{1}{4}$ S BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, crew - Feb. 1966 - C.S. File 54/20-17

Found - 8" Fir stump for corner tree.

30" Fir, down, N.33 $\frac{1}{2}$ °W., 25.1 ft., opened for scribe "S".

30" now 37" Fir, N.35 $\frac{1}{4}$ °E., 26.4 ft., shows good scar.

Set Brass cap at cor. mkd: County Surveyors Office

T 31 S R 4 W

$\frac{1}{4}$ S31|S32

1966

New BT - 13" Laurel N.2°E., 47.7 ft. scribed $\frac{1}{4}$ S32 CS BT.

Cap is 1.0 ft. North of corner tree stump because of roots.

Bruce Shaner - For: Seneca Jones Timber Co. - 12/96 - C.S. File 65/13-1 J - R.M. 4-3

Found - 8" D.Fir stump, mostly gone.

Reset the 2 $\frac{1}{2}$ " brass cap on a 1"x30" ironpipe in position of the 8" D.Fir corner tree, from which:

30" D.Fir, bearing N.33 $\frac{1}{2}$ °W., 25.1' is now gone.

18" Madrona (Laurel), I rescribed bark " $\frac{1}{4}$ S32 BT" bears N.2°E., 47.7'.

New accessories -

8" D.Fir, scribed " $\frac{1}{4}$ S31 BT" bears S.67°W., 24.3'.

6 foot steel fence post, North, 1.0 foot.

Note - Corner is East, 60 feet from rock road USBLM road.

Found OK by R. Rice, Feb. 2004 - M144-9