

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 200340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 19 and 20

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7860)

A Cedar 5" dia., which I mark $\frac{1}{4}$ S on W. face, for $\frac{1}{4}$ sec. cor., from which

A Cedar 5" dia., bears S.19 $\frac{1}{4}$ °W., 6 $\frac{1}{4}$ lks. dist. mkd. $\frac{1}{4}$ S BT.

A Cedar 5" dia., bears S.53 $\frac{1}{2}$ °E., 14 $\frac{3}{4}$ lks. dist. mkd. $\frac{1}{4}$ S BT.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. - Wit: J.R. Markham - Oct. 7, 1959 - C.S. File 42/391-37

Determined by O.B.T.s

At corner point found 7" Cedar, uproot, scribed $\frac{1}{4}$ S on West face and SET 3/4" x 40" Iron rod, from which

10" Cedar bears S.48°W., 11.8 ft. mkd. $\frac{1}{4}$ S19 BT.

10" Fir bears N.61°E., 26.8 ft. mkd. $\frac{1}{4}$ S20 BT.

10" Fir bears N.6°W., 61.0 ft. mkd. $\frac{1}{4}$ S19 BT.

Corner lies on South edge of road on top of main ridge.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, crew - Feb/March 1966 - C.S. File 54/20-21

Found - No trace of iron rod as recorded by Markham.

10" Cedar, now snag, S.48°W., 11.8 ft. scribing visible.

10" Fir now 13", N.61°E., 26.8 ft., shows good scar.

10" Fir now 12", N.6°W., 61.0 ft., shows good scar.

Set Brass cap at cor. mkd: County Surveyors Office

T 31 S R 4 W

$\frac{1}{4}$ S19 | S20

1966

Cedar post alongside.

All BTs in good condition.

Corner lies on South edge of Jeep road.

Douglas County Surveyors Office - Gregory E. Quibell, Deputy - Debbie Stewart, Wit. - July 14, 1981 - C.S. File 61/27-18

Found - Brass cap on 1" I.P. which protrudes 9" above ground and leans slightly to the South. The cap is marked: County Surveyors office 1/4 19 20 1966.

(The line on the cap, between 19 and 20, points N.80°E., rather than North.) No other monument was found.

(Cont. Next Page)

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 200340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 19 and 20

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

11" Cedar, orig. 10", snag, 7 ft. tall, with scribed "¼ S19" visible, bears S.64°W., 11.1 ft. (Rec. S.48°W., 11.8 ft.)
14" Fir, orig. 10" bears N.52°E., 28.1 ft. (Rec. N.61°E., 26.8 ft.) with well healed blaze.
15" Fir, orig. 10", bears N.8°W., 65.2 ft. (Rec. N.6°W., 61.0 ft.) with well healed blaze.

Since the bearings and distances disagree badly with record calls, I do NOT accept the position of the found brass cap as the true corner. I REMOVE said brass cap from the 1" I.P., leaving said pipe in place, protruding 7" above ground to preserve its position, and bearing S.21°E. 3.65 ft. from "set B.C.". I then use the three (3) existing BTs and establish a position for the corner, which closely matches record calls. I SET a brass cap mkd: Douglas Co Surveyor
T 31 S R 4 W
¼ S19 | S 20
1981

from which the 3 existing BTs bear as follows:
11" orig. 10", Cedar snag bears S.48°W., 12.0 ft. (rec. 11.8 ft.)
14", orig. 10", Fir bears N.61°E., 27.1 ft. (Rec. 26.8 ft.)
15", orig. 10", Fir bears N.6°W., 61.5 ft. (Rec. 61.0 ft.) This distance was difficult to measure exact due to log deck on line.

New BTs- 24" Fir bears S.80°W., 72.2 ft. scribed "¼ S19 CS BT" in double blaze.
8" Fir bears S.26°W., 17.1 ft. scribed "¼ S19 CS BT" in double blaze.

All trees have new DCS0 BT tags.
Corner lies on southerly edge of dirt road (31-4-192) and has a fence post with survey marker sign 0.6 ft. southerly of cap.

Fd. Ok by Tony Hostetter, 11/2007 - M154-51