

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 200440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 17 and 18

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7864)

-----  
A Fir 15" dia., which I mark  $\frac{1}{4}$  S on W. face for  $\frac{1}{4}$  sec. cor., from which

A Fir 30" dia., bears S.50 $\frac{1}{2}$ °W., 7 $\frac{1}{2}$  lks. dist. mkd.  $\frac{1}{4}$  S BT.

A Laurel 5" dia., bears N.52 $\frac{1}{4}$ °E., 27 lks. dist. mkd.  $\frac{1}{4}$  S BT.

Survey by Robert M. Thompson - For: Sunny Valley Lumber Co. - July 12, 1959 - M 15-24

-----  
Found - Fir corner tree in good condition.  
SW. Fir BT, per govt. notes, in good condition.  
Other orig. BT, rotted out.

Scribed- 10" Hemlock N.17°E., 22.0 ft.