

PRIMARY CORNER DESCRIPTION Sec. Cor. for 7, 8, 17 and 18

| Alias | Description |
|-------|-------------|
| Alias | Description |
| Alias | Description |
| Alias | Description |

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 19 Page(s) 7864)

Set a stone 14x8x4 ins., 10" in the ground for cor. to secs. 7, 8, 17 and 18, marked with 5 notches on E. and 4 notches on S. edges; from which

A Hemlock 5" dia., bears N.71½°E., 7½ lks. dist. mkd. T31S R4W S8 BT.

A Hemlock 5" dia., bears S.36 3/4°E., 10 lks. dist., mkd. T31S R4W S17 BT.

A Hemlock 10" dia., bears S.64°W., 7 lks. dist. mkd. T31S R4W S18 BT.

A Dogwood 10" dia., bears N.13½°W., 16 lks. dist. mkd. T31S R4W S7 BT.

Survey by Robert M. Thompson - For: Sunny Valley Lumber Co. - July 12, 1959 - M 15-24

Found - Stone with notches per govt. notes, but broken in two.
All BTs rotted out, but rotted stumps for 3 Hemlocks present.

Scribe - 7" D.Fir N.73°20'W., 17.5 ft.
36" D.Fir N.64°E., 41.2 ft.
13" D.Fir S.42°40'E., 13.5 ft. with alum. tag.
14" D.Fir S.17°W., 42.5 ft.

David Edwards - Roseburg Resources - Aug. 2005 - C.S. 65/55-7

Found - Broken stone & 7/8" dia iron pipe
42" dia. fir N.64°E., 41.2' with bark scribe
25" dia. fir S.42°40'E., 13.5' with healed blazes.
25" dia. fir S.17°W., 42.5' with healed blazes.
15" fir N.73°20'W., 17.5' with healed blazes.

FD. Ok by T Hostetter, 4/2006 - M154-42

Tony Hostetter - For: Roseburg Resources - Jan. 2011 - M162-3

Found: 7/8" iron pipe & accessories as described in 2007, M154-42