

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 200540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 7 and 8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 19 Page(s) 7869)

A Fir 10" dia., which I mark ¼ S on W. face for ¼ sec. cor., from which

A Fir 20" dia., bears N.47½°W., 13 lks. dist., mkd. ¼ S BT.

A Fir 10" dia., bears N.22½°E., 13½ lks. dist. mkd. ¼ S BT.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. - Wit: R.G. Boyd; O.A. Keatley; J.L. Markham - Aug. 18, 1959 - C.S. File 42/391-32

Determined by O.B.T.s:

14" Fir S.47°E., 8.6 ft., found scribe.

At corner point found 40" Fir mkd. East on face and SET 3/4" x 36" Iron pipe, from which

24" Fir bears S.69°W., 29.0 ft. mkd. ¼ S7 BT.

30" Fir bears N.85°W., 15.3 ft. mkd. ¼ S7 BT.

80" Cedar bears N.63°W., 25.0 ft. mkd. ¼ S7 BT.

20" Fir bears N.32°W., 15.3 ft. mkd. ¼ S7 BT.

Corner lies on top of side ridge.

David Edwards - Roseburg Resources - Aug. 2005 - C.S. 65/55-7

Found - 38" dia. corner fir.

A 3/4" dia. iron pipe bears south 2.4'

29" fir bears S.69°W., 29.0'

30" fir bears N.85°W., 15.3'

80" cedar N.63°W., 25.0'

21" dia. fir bears N.32°W., 15.3'

Firs are bark scribed.

Cedar has no visible marks.