

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 240500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 17

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 19 Page(s) 7865)

A Fir 36" dia., which I mark ¼ S on N. face for ¼ sec.cor., from which

A Fir 26" dia., bears S.34°E., 29 lks. dist. mkd. ¼ S BT.

A Fir 31" dia., bears N.73°W., 55½ lks. dist. mkd. ¼ S BT.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. -
Wit: R.G. Boyd; O.A. Keatley; J.L. Markham - Aug. 18, 1959 -
C.S. File 42/391-31

Determined by O.B.T.s:

34" Fir S.29°E., 19.0 ft.

40" Fir N.65°W., 36.0 ft.

At corner point, found 40" Fir mkd. on North face and SET 1" x 30" Iron pipe, from which

5" Cedar bears N.43°W., 23.0 ft. mkd. ¼ S8 BT.

6" Cedar bears S.37°E., 38.4 ft. mkd. ¼ S17 BT.

4" Cedar bears N.37°E., 22.0 ft. mkd. ¼ S8 R4W BT.

4" Laurel bears S.75°W., 18.5 ft. mkd. ¼ S17 BT.

50" Fir bears S.64°E., 11.6 ft. mkd. ¼ S17 BT.

Tony Hostetter - For: Roseburg Resources - Jan. 2011 - M162-3

Found - 1" iron pipe on North side of a 40" fir which was identified as the original corner tree by J.H. Markham in 1959 C.S. 42/391. From which:

40" fir, BT tag, GL0 BT bears: S.29°E., 19.0 ft.

12" cedar, Markham BT, bears: S.37°E., 38.4 ft

50" fir, BT TAG, Markham BT, bears: S.64°E., 11.6 ft