

PRIMARY CORNER DESCRIPTION Sec. Cor. for 20, 21, 28 and 29

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 18 Page(s) 7790)

-----  
Set post cor. to secs. 20, 21, 28 and 29, from which  
A Laurel 8" dia., bears N.75°E., 45 lks. dist.  
A Laurel 10" dia., bears S.15°E., 32 lks. dist.  
A Laurel 10" dia., bears S.62°W., 66 lks. dist.  
A Chinquapin 12" dia., bears N.58°W., 15 lks. dist.

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7836)

-----  
The sec. cor., which is a post, 4" sq., greatly decayed, with marks nearly obliterated. I find 2 of the original witness trees standing.

I remove this post and set a Fir post, 4 ft. long, 4" sq., 24" in the ground, for cor., marked with 4 notches on E. and 2 notches on S. edges; from which

A Laurel 8" dia., (10" now) bears N.75°E., 45 lks. dist. mkd. T31S R4W S21 BT.  
A Chinquapin 12" dia., bears N.58°W., 15 lks. dist. mkd. T31S R4W S20 BT.

The Laurel witness trees in secs. 28 and 29 have been destroyed by fire.

I mark 2 trees as follows:

A Fir 17" dia., bears S.34½°E., 49½ lks. dist. mkd. T31S R4W S28 BT.  
A Fir 6" dia., bears S.15½°W., 37½ lks. dist. mkd. T31S R4W S29 BT.

Douglas County Surveyors Office - G.J. Wenderoth, Deputy - Wit: F. Loso - Nov. 1949 - C.S. File 40/245

-----  
Found - 20" Chinquapin N.58°W., 9.9 ft., burned.  
36" Fir S.34°30'E., 32.6 ft., cut.  
Other trees gone.

Drive 1¼" I.Pipe, from which scribed:

18" Fir S.53°23'E., 49.0 ft.  
28" Fir S.30°40'W., 27.4 ft.  
9" Fir N.58°00'W., 30.0 ft.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, crew - Jan/Feb. 1966 - C.S. File 54/20-14

-----  
Found - I.Pipe at sec. corner.  
18" Fir now 24", N.31½°E., 13.1 ft. shows good scars  
(Cont. Next Page)

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 300300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 20, 21, 28 and 29

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

18" Fir now 24", S.53½°E., 49.0 ft., shows good scars, pitched over scribing visible "2".  
28" Fir now 31", S.30½°W., 27.4 ft., shows good scars.  
9" Fir now 16" N.58°W., 30.0 ft., shows good scars  
Set Brass cap at cor. mkd: County Surveyors Office  
T 31 S R 4 W  
S 20 | S 21  
S 29 | S 28  
1966

Brass cap set alongside iron pipe.  
All BTs in good condition.  
This corner lies North of ridge top about 100 ft.

Fd. and Used in BLM Resurvey by Lynn M. Roseberry and Larry D. Evans, Cadastral Surveyors, under Group #778, surveyed July/Sept. 1972- (DCSO records Vol. 38 Page(s) 15486-87)

Fd. Ok by Tony Hostetter, 11/2007 - M154-51

Ron Rice - For Seneca Jones Timber Co. - 6/2008 - M156-22  
-----  
Found - 2½" DCBC dated 1966 with the following accessories:  
47" D.Fir bears S.30½°W., 30.0' - healed face [rec S.30½°W., 27.4']  
37" D.Fir bears S.53½°E., 49.0' - healed face  
32" D.Fir bears N.58°W., 30.0' - healed face  
26" chinquapin bears N.29°W., 9.9' - burned face [record N.58°W. 9.9']

Fd. BC & BTs per rec. 2/2016 - By C. Sweeden