

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 21 and 28

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 18 Page(s) 7791)

Set ¼ sec. post, from which
 A Laurel 10" dia., bears N.5°W., 52 lks. dist.
 A Chinquapin 8" dia., bears S.10°W., 32 lks. dist.

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7835-36)

The ¼ cor., which is a post greatly decayed with marks nearly obliterated, I find the 2 witness trees broken off about 12 ft. above ground.
 At cor. point, Set a Fir post, 4 ft. long, 4" sq., 24" in the ground, for ¼ sec. cor., marked ¼ S on N. face; from which
 A Laurel 10" dia., bears N.5°W., 52 lks. dist. mkd. ¼ S BT
 A Chinquapin 8" dia., bears S.10°W., 32 lks. dist. mkd. ¼ S BT.

I mark 2 new trees as follows:
 A Fir 6" dia., bears S.23°E., 49 lks. dist. mkd. ¼ S BT.
 A Fir 11" dia., bears N.60°E., 38½ lks. dist. mkd. ¼ S BT.

Douglas Co. Surveyors Office - Ben B. Irving, Deputy - Wit: N.E. Richardson; N.H. Haskell; Ellis Bushman - Nov. 10, 1937 - C.S. File 53/99

Set Yewwood post 4" dia., 36" long, 12" in ground from BTs as described in government field notes. One tree broken off and rotten. Post scribed ¼ S C.S. on E. face; S21 on N. face; S28 on S. face.
 New BTs- Fir 22" dia. N.38°W., 51½ lks. mkd. ¼ S21 CS BT.
 Fir 32" dia. S.67½°E., 58 lks. mkd. ¼ S28 CS BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, crew - March 1966 - C.S. File 54/20-27

Found - 22" now 27" Fir, N.38°W., 34.0 ft., bark scribed "¼S" visible.
 32" now 38" Fir, S.67½°E., 38.2 ft., bark scribed "CS BT".
 Yewwood post at ¼ corner.
 Set Brass cap at cor. mkd: County Surveyors Office
 T 31 S R 4 W
 ¼ S 21
 S 28
 1966

(Cont. Next Page)

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 340300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 21 and 28

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Rescribed and reblazed:

27" D.Fir N.38°W., 43.0 ft. mkd. ¼ S21 CS BT.

38" D.Fir S.67½°E., 38.2 ft. mkd. ¼ S28 CS BT.

Fd. and Used in BLM Resurvey by Lynn M. Roseberry and Larry D. Evans, Cadastral Surveyors, under Group #778, surveyed July/Sept. 1972- (DCSO records Vol. 38 Page(s) 15488)

Carl Sweeden - For: Perpetua Forest Co. - 2/2016 - M170-45

Found - 2½" 1966 DCSO BC marked per record

26" D.Fir BT stump, N.36°W., 35.2' (rec. N.36°W., 53 lks) very rotted w/rooted blaze, no marks vis.

42" D.Fir BT stump, S.71¼°E., 56 lks, healed blaze

New - 10" D.Fir BT, N.64¼°W., 23.5', dbl blazed & scribed "¼ S 21 BT", mag nail wi brass washer "LS 2752" in face.

7" D.Fir BT, N.11¾°E., 24.7', dbl blazed & scribed "¼ S 21 BT", Mag nail wi brass washer "LS 2752" in face.

5/8"x30" I.Rod w/ red plastic cap "SWEEDEN LS 2752" S.37°54'37"E., 14.86'

5/8"x30" I.Rod W/ red plastic cap "SWEEDEN LS 2752", S.46°32'09"W., 15.65'