

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 340400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 16 and 21

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7838)

Set a stone 14x10x6 ins., 10" in the ground for 1/4 sec. cor. marked 1/4 on N. face, from which
A Fir 11" dia., bears N.38 1/2°E., 33 1/2 lks. dist. mkd. 1/4 S BT
A Fir 17" dia., bears S.29 1/4°W., 44 lks. dist. mkd. 1/4 S BT.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. - Wit: R.G. Boyd - Oct. 16, 1958 - C.S. File 42/391-4

Determined by O.B.Ts:
20" Fir stump bears N.38 1/2°E., 22.0 ft.
22" Fir snag bears S.29°W.,
At corner point, SET 40" steel fence post, from which
26" Fir bears N.69°W., 67.0 ft. mkd. 1/4 S16 BT.
16" Fir bears N.5°E., 213.0 ft. mkd. 1/4 S16 BT.
Road bears N.45°W., 135.0 ft. dist.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, crew - March 1966 - C.S. File 54/20-6

Found - Steel fence post at 1/4 corner.
26" Fir now 27", N.69°W., 67.0 ft., pitched over, scribing visible.
16" Fir N.5°E., 213.0 ft., pitched over, scribing visible.
Orig. 22" Fir stump S.29°W., 29.0 ft.
Set Brass cap at cor. mkd: County Surveyors Office
T 31 S R 4 W
1/4 S 16
S 21
Bearing trees in good condition.

Mark Smalley - For: Roseburg Resources - 3/29/2000 - C.S. File 65/37-27

Found - 1966 DCSO IPBC solid in ground
"T" post - top 12" above ground.
New BTs- 11" Fir N.75°E., 21.7 ft. scribed "1/4 S BT"
11" Fir S.28°E., 13.3 ft. scribed "1/4 S BT"
14" Fir S.73°W., 20.5 ft. scribed "1/4 S BT"
16" Fir N.24°W., 17.1 ft. scribed "1/4 S BT"

continued next page

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 340400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 16 and 21

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Dependent retracement by A Bert Skeesick Cadastral Surveyor, and Robert H. Browning, Surveying Technician, Group No. 2300 surveyed Jun/July 2008 - (DCSO records 2010-1 plat & copy of map in Vol. 56 Page(s) 21926-7)

The ¼ sec. cor. of secs. 16 and 21, perpetuated by Markham, in 1958, further perpetuated by the Douglas County Surveyors Office in 1966, and further perpetuated by Smalley, in 2000, monumented with an iron post, ¼" dia., firmly set, projecting 10" above the ground, with brass cap (properly) mkd.

from which the remains of an original bearing tree
A sawed fir stump, 23" dia., bears S.29¼°W., 29.0 ft., with fragmentary scribe marks visible on a partially healed blaze.

and the remains of a bearing tree mkd. by Markham
A fir snag. 26" dia., bears N.69°W., 64.5 ft., with a healed blaze.

and bearing trees mkd. by Smalley
A fir, 12" dia., bears N.70°E., 21.6 ft., with a healed blaze.

A fir, 13" dia., bears S.29¼°E. 3.0 ft., with a healed blaze.

A fir, 17" dia., bears S.70¼°W., 20.6 ft., with a healed blaze.

A fir, 19" dia., bears N.28°W., 17.1 ft., with a healed blaze.

Latitude 42°52'14.23"N Longitude 123°10'48.73"W
(NAD 1983 (CORS 96))