

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 340600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7843)

-----  
Set a stone 14x10x5 ins., 10" in the ground, for 1/4 sec. cor. marked 1/4 on N. face; from which

A Fir 15" dia., bears S.32 1/2°W., 39 1/2 lks. dist. mkd. 1/4 S BT.

A Fir 12" dia., bears N.58 1/2°W., 56 1/2 lks. dist. mkd. 1/4 S BT.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. - Wit: Vaughn - Aug. 16, 1951 - C.S. File 40/363

-----  
Set by proportional measurement.

At corner point, SET 3/4" x 35" Iron pipe, from which

A Fir 33" dia., bears S.61°E., 28.5 ft. mkd. 1/4 S9 BT.

A Fir 36" dia., bears N.21°E., 9.5 ft. mkd. 1/4 S4 T31S R4W BT.

Logging road bears West, 206.0 ft. dist.

Douglas Co. Surveyors Office - M. Lenora Ladig; P.L. Earle; Crew - June 7, 1976 - C.S. File 59/15-12

-----  
Found - Two 3/4" I.P.'s at corner, from which

33" now 36" dead Fir snag bears S.61°E., 28.5 ft. with "1/4 S9 BT" in visible bark scribe.

36" now 40" dead Fir snag bears N.21°E., 9.5 ft. with "1/4 S9 T31S R4W BT" in visible bark scribe.

Set 1" x 36" I.P. with brass cap mkd: Douglas County Surveyor T31S R4W

1/4  $\frac{S4}{S9}$  1976

Placed both 3/4" iron pipes on North side of cap.

New BTs- 8" D.Fir bears S.36°E., 23.1 ft. scribed "1/4 S9 CS BT" in double blaze.

6" D.Fir bears N.10°W., 11.2 ft. scribed "1/4 S4 CS BT" in double blaze.

Corner lies approx. 200 ft. East of Rd. #30-4-28.0

BLM resurvey by Wayne L. Rogers, Rick A. McMullen, Lance J. Bishop, Cadastral Surveyors, under Group #1217, surveyed Sept. 1984/April 1986 - (DCSO records Vol. 47 Page(s) 18150-51)

-----  
Point for the 1/4 sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an stainless steel post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd: (Cont. Next Page)

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

T 31 S R 4 W  
¼  $\frac{S\ 4}{S\ 9}$   
1985

from which  
A Fir 14" dia., bears S.44°E., 46 lks. dist. mkd. ¼ S9 BT.  
A Fir 10" dia., bears N.20 ¾°W., 32 lks. dist. mkd. ¼ S4 BT.  
Deposit white "DEEP-1" magnetic marker at base of stainless steel post.

From this point, a point established and recorded by Markham in 1951, subsequently perpetuated and recorded by Ladig in 1976, bears N.35°19'E., 0.303 chs. dist., monumented with an iron post, 2½" dia., firmly set, projecting 4" above ground (alongside are two iron pipes, 1" dia., both firmly set,) with brass cap mkd. T31S R4W ¼ S4 S9 1976, from which the remains of the bearing trees mkd. by Markham:  
A Fir snag 42" dia., bears N.19°E., 16 lks. dist. with fragmentary scribe marks ¼ S4 T31S R4W visible.  
A Fir snag 42" dia., bears S.61°E., 44 lks. dist., no marks visible.  
and the remains of the bearing trees mkd. by the County:  
A Fir snag 11" dia., bears S.40°E., 35 lks. dist., with pitched over blaze.  
A Fir snag 6" dia., bears N.10°W., 17 lks. dist. with fragmentary scribe marks visible.

---

Mark Smalley - For: Roseburg Resources - 9/7/2001 - C.S. File 65/37-16  
-----  
Found - 1985 BLM IPBC  
1976 DCSO IPBC  
2¾" I. pipes, next to DCSO IPBC  
21" Fir, S.44°E., 30.4 good condition - healed face.  
17" Fir, N.20¾°W., 21.1 good condition - healed face  
New BTs- 10" Fir, S.56°E., 25.8 scribed "¼ S BT"  
9" Fir, N.50°W., 16.7 scribed "¼ S BT"

---

Found OK by J. Estabrook, May 2003 - M142-36 & CS65/45-32H

---

Greg Lang - 12/31/2013 - C.S. File 65/82-6  
-----  
Found - 1985 BLM brass cap set by proportion in 1985.  
21" Fir bears S.44°E., 30.40' (record S.44°E 30.40')  
17" Fir (dead) bears N.20°W. 21.10' (record N.20¾°W. 21.10')  
continued next page

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 340600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

1½" IP bears N.35¼°E., 20.20' (County's brass cap has apparently been sawn off leaving only this pipe).  
New - A 22" fir bears S.71¼°W., 16.50' scribed "¼ S9 BT"  
A 9½" fir bears N.14°W., 30.80' scribed "¼ S4 BT"  
Note - Bearings are to the center of the trees and distances are measured to a spike in the side of the trees.  
Corner lies on a steep East slope about 180' below and East of gravel road.