

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 400140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 33 and 34

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 18 Page(s) 7787)

-----  
Set ¼ sec. post, from which  
A Laurel 8" dia., bears S.80°E., 27 lks. dist.  
A Laurel 6" dia., bears S.80°W., 26 lks. dist.

Frank Cain - Sept. 20, 1909 - Field Book 10 Page 51½

-----  
Set post for ¼ cor. on East bdy. of sec. 33, from which  
A Fir 36" bears N.63½°W., 79 lks.  
A Fir 20" bears N.17¼°E., 65 lks.

Douglas Co. Surveyors Office - G.J. Wenderoth, Deputy - Wit:  
F. Loso - March 1949 - C.S. File 40/245

-----  
Find both old BTs as set by Cain in 1909, one dead:  
40" Fir N.60°12'W., 52.1 ft.  
14" Fir S.6°06'E., 54.0 ft.  
Drive 1" Iron pipe for corner.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & J. Brady, crew - Feb. 1966 - C.S. File 54/20-9

-----  
Found - No trace of iron pipe as recorded.  
40" Fir now snag, N.60°W., 52.1 ft. Tree badly  
burned but some scribe marks still visible.  
14" Fir S.6°E., 54.0 ft., no trace found.

Set Brass cap at cor. mkd: County Surveyors Office  
T 31 S R 4 W  
S 33 | S 34  
1966

New BTs- 17" Fir S.42°W., 33.4 ft. scribed ¼ S33 CS BT.  
8" Fir N.37°E., 67.4 ft. scribed ¼ S34 CS BT.  
This corner falls in skid road.

Fd. and used in BLM Resurvey by Lynn M. Roseberry and Larry D. Evans, Cadastral Surveyors, under Group #778, surveyed July/Sept. 1972- (DCSO records Vol. 38 Page(s) 15474)