

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 9, 10, 15 and 16

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7830)

-----  
Set a stone 14x10x8", 10" in the ground, for cor. to secs. 9, 10, 15 and 16, marked with 3 notches on E. and 4 notches on S. edges; from which

A Fir 6" dia., bears N.66°E., 35 lks. dist. mkd. T31S R4W S10 BT.

A Laurel 10" dia., bears S.53 3/4°E., 63 lks. dist., mkd. T31S R4W S15 BT.

A Fir 40" dia., bears S.57°W., 17 lks. dist. mkd. T31S R4W S16 BT.

A Fir 10" dia., bears N.77½°W., 70 lks. dist. mkd. T31S R4W S9 BT.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. - Wit: Geo. Vaughn and Bill Vaughn - May 20, 1951 - C.S. File 40/232

-----  
Determined by original bearing tree:

A Fir 12" dia., bears N.66°E., 23.0 ft.

A Fir 50" dia., bears S.57°W., 11.0 ft.

At corner point, found two wood stakes together. Drove 1" x 30" iron pipe.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, crew - April 1966 - C.S. File 54/20-46

-----  
Found - Iron pipe and stone with notches.

50" Fir S.57°W., 11.0 ft., shows good scar.

12" Fir, down and rotten, N.77½°W., 46.2 ft.

12" Fir now 18", N.66°E., 23.0 ft., shows good scar.

No trace of Laurel BT.

Set Brass cap at cor. mkd: County Surveyors Office

T 31 S R 4 W

S 9 | S 10

S 16 | S 15

1966

New BT - 23" Cedar S.49°E., 17.0 ft. scribed T31S R4W S15 CS BT.

Reblaze and rescribe:

18" D.Fir N.66°E., 23.0 ft. scribed T31S R4W S10 CS

BT.

(Cont. Next Page)

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 9, 10, 15 and 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM resurvey by Wayne L. Rogers, Rick A. McMullen, Lance J. Bishop, Cadastral Surveyors, under Group #1217, surveyed Sept. 1984/April 1986 - (DCSO records Vol. 47 Page(s) 18148)

-----  
The Sec. cor., perpetuated and recorded by Powell in 1966, monumented with an iron post, 1½" dia., firmly set, projecting 12" above ground, with 1966 brass cap from which the original bearing trees:

A Fir 23" dia., bears N.66°E., 35 lks. with healed blaze.

A Fir 50" dia., bears S.57°W., 17 lks. with healed blaze.

and bearing trees mkd. by Powell:

A Cedar 23" dia., bears S.49°E., 24 lks. with healed blaze and a new bearing tree:

A Fir 7" dia., bears N.14½°W., 44 lks. mkd. T31S R4W S9 BT

BLM Dependent resurvey by Timothy J. Moore, Cadastral Surveyor and Robert H. Browning, Surveying Technician under Group #1941, surveyed March/Sept. 2000. (DCSO rec. Vol. 53 page(s) 20719)

-----  
The cor. of secs. 9, 10, 15, & 16, monumented with an iron post, 1½" diam., loosely set, projecting 18" above ground, (with an iron post, 1½" diam., driven alongside, projecting 14" above ground, & the original basalt stone, 12x7x6", mkd. with 3 & 4 notches lying loose alongside) with 2½ in. brass cap (properly) mkd.

from which the remaining original bearing trees

A fir, 28" dia., bears N.66°E., 23.1 ft., with a healed blaze.

A fir, 50" dia., bears S.57°W., 11.2 ft., with a healed blaze.

and a bearing tree mkd. by Powell, Jones, & Brady, of the Douglas County Surveyors Office

A cedar, 27" dia., bears S.46¾°E., 15.8 ft., with a healed blaze. (Record, S.49°E.)

and a bearing tree mkd. by Rogers, McMullen, & Bishop

A fir, 14" dia., bears N.14½°W., 29.0 ft., with a healed blaze.

Reset the 1½ X 20" iron post, 18" in the ground, deposit the original quartz stone & the 1 X 20" iron pipe set by Markham Jr. in 1959 along side the iron post.

Cor. is located on a N. slope, 20 ft. N. of an overgrown skid road, 15 ft. wide, bears S.50°E., N.50°W.

Fd. Ok by C Sweeden, July 2013 - M165-56

continued next page

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 9, 10, 15 and 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

David Edwards - Crew: Brant Miller - Jan. 2022 - C.S. File 65/109-57

-----  
Found - The 1966 D.C.S. pipe/cap. Removed it and set a 5/8" steel rebar at the corner position 12" deep to avoid logging damage.  
Replaced the pipe/cap at position of undisturbed rebar after logging was complete.  
A 31" dia. Fir stump w/scar and tag bears N.66°E., 23.1 ft.  
A 30" dia. Cedar stump w/scar and tag bears S.47°E., 15.80 ft.  
A 51" dia. Fir stump w/scar and tag bears S.57°W., 11.2 ft.  
An 18" dia. Fir stump w/scar and tag bears N.14°W., 29.0 ft.  
Monument is a Standard D.C.S. brass capped iron pipe.  
New - 5.5 ft steel posts are set 2 ft from the monument in all four cardinal directions.  
Compass Declination 15° East