

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 400600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3, 4, 9 and 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7832)

Set a stone 14x12x6 ins., 10" in the ground, for cor. to secs. 3, 4, 9 and 10, marked with 3 notches on E. and 5 notches on S. edges; from which

A Fir 30" dia., bears N.15°E., 51 lks. dist. mkd. T31S R4W S3 BT.

A Laurel 6" dia., bears S.66½°E., 22 lks. dist. mkd. T31S R4W S10 BT.

A Fir 18" dia., bears S.20°W., 82 lks. dist. mkd. T31S R4W S9 BT.

A Fir 14" dia., bears N.81 3/4°W., 91 lks. dist. mkd. T31S 4W S4 BT.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. - Wit: R.G. Boyd - March 9, 1960 - C.S. File 42/391-53

Determined from O.B.T.s:

33" Fir N.15°E., 33.6 ft.

40" Fir S.20°W., 54.0 ft., found scribe.

26" Fir N.79°W., 60.0 ft., found scribe.

At corner point, found stone and SET 1/2" x 30" Iron pipe, from which

7" Laurel bears N.9°W., 23.5 ft. "S4 T31S R4W BT"

8" Laurel bears N.67°E., 28.6 ft. "S3 T31S R4W BT"

6" Chinquapin bears S.38°E., 16.0 ft. "S10 R4W BT"

Douglas Co. Surveyors Office - M Lenora Ladig; P.L. Earle, crew - May 25, 1976 - C.S. File 59/15-9

Found - A 1/2" Iron pipe with orig. 14"x12"x6" stone on North side. Found on stone: 3 notches on East edge and 5 notches on North edge.

An orig. 30" now 48" Fir bears N.15°E., 33.6 ft. Tree alive with healed blaze.

An orig. 18" now 40" Fir bears S.20°W., 54.0 ft. Tree alive. Blaze has been opened and scar is pitched over.

An orig. 14" now 26" Fir bears N.79°W., 60.0 ft. Tree alive. Blaze has been opened and scar is pitched over.

An 8" now 12" Laurel bears N.67°E., 28.6 ft. with "S3 T31S R4W BT" visible bark scribe. Tree is alive.

At true corner point, SET a 1P" x 36" I.Pipe with brass cap stamped: (Cont. Next Page)

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 400600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3, 4, 9 and 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>Douglas Co. Surveyor T 31 S R 4 W S 4 S 3 S 9 S 10 1976</p> <p>Placed stone on North side of cap and 1/2" I.P. on South side of cap. Did not scribe a SE. BT as area is a clear cut. Corner lies 100 ft. North of Rd. #31-4-3.0.</p>
<p>Cor. Fd. and used in BLM resurvey by Wayne L. Rogers, Rick A. McMullen, Lance J. Bishop, Cadastral Surveyors, under Group #1217, surveyed Sept. 1984/April 1986 - (DCSO records Vol. 47 Page(s) 18149-50)</p>
<p>Mark Smalley - For: Roseburg Resources - 9/7/2001 - C.S. File 65/37-17</p> <p style="text-align: center;">-----</p> <p>Found - 1" DCSO IPBC Stone partially buried. 1/2" IP 32" Fir N.79°W., 60.0 fair condition - healed face. (Orig.) 44" Fir S.20°W., 54.0 fair condition - healed face. (Orig.) 16" Laurel N.67°E., 28.6 fair condition - healed face. (Orig.) New BTs- 6" Fir N.80°E., 17.4 scribed "S3 BT"</p>
<p>Fd. Ok by C Sweeden, July 2013 - M165-56</p>
<p>Greg Lang - 12/31/2013 - C.S. File 65/82-8</p> <p style="text-align: center;">-----</p> <p>Condition report only Found 1976 Douglas Co. brass cap. Found all four BTs recorded by Mark Smalley in 2001 Note - Corner lies approx. 100' north of gravel road which can be accessed from Shively Creek.</p>