

PRIMARY CORNER DESCRIPTION 1/4 Cor for Secs. 22 and 27

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 18 Page(s) 7789)

-----  
Set ¼ sec. post, from which  
A Fir 8" dia., bears N.62°E., 15 lks. dist.  
A Fir 8" dia., bears S.25°W., 6 lks. dist.

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7826)

-----  
The ¼ sec. cor., which is a post, 4" sq., greatly decayed, marked ¼ S on N. face, I find the 2 witness trees. I remove this post and set a Fir post, 4 ft. long, 4" sq., 24" in the ground, for ¼ sec. cor. marked ¼ S on N. face; from which  
A Fir 8" dia., (10" now) bears N.62°E., 15 lks. dist., marked ¼ S BT.  
A Fir 8" dia., bears S.25°W., 6 lks. dist. marked ¼ S BT.

Douglas Co. Surveyors Office - George Wenderoth, Deputy - Dec. 1947 - C.S. File 40/29 and M 4-75

-----  
Found both trees in good shape, Drove a 1" I.Pipe for the cor.  
20" Fir bearing N.62°E., 9.9 ft. dist.  
18" Fir bearing S.25°W., 4.4 ft. dist.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, crew - Feb. 1966 - C.S. File 54/20-18

-----  
Found - I.Pipe at ¼ corner.  
Orig. 10" now 26" Fir, N.62°E., 9.9 ft., shows good scar.  
Orig. 8" now 22" Fir, S.25°W., 4.0 ft. tree has been opened, shows scribe "S".

Set Brass cap at cor. mkd: County Surveyors Office  
T 31 S R 4 W  
¼  $\frac{S\ 22}{S\ 27}$   
1966

Both BTs in good condition. No new BTs.

Fd. and Used in BLM Resurvey by Lynn M. Roseberry and Larry D. Evans, Cadastral Surveyors, under Group #778, surveyed July/Sept. 1972- (DCSO records Vol. 38 Page(s) 15480)

Found OK by Max Hull, April 2006 - M150-45