

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 15 and 22

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7829)

-----  
Set a Fir post, 4 ft. long, 4" sq., 24" in the ground, for 1/4 sec. cor. marked 1/4 S on N. face; from which  
A Fir 7" dia., bears N.10 1/4°E., 8 1/4 lks. dist. mkd. 1/4 S BT.  
A Fir 5" dia., bears S.36 1/2°W., 12 1/2 lks. dist. mkd. 1/4 S BT

BLM resurvey by Wayne L. Rogers, Rick A. McMullen, Lance J. Bishop, Cadastral Surveyors, under Group #1217, surveyed Sept. 1984/April 1986 - (DCSO records Vol. 47 Page(s) 18146)

-----  
Point for the 1/4 sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an stainless steel post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd: T 31 S R 4 W

1/4 S 15  
S 22  
1985

from which

A Fir 13" dia., bears N.84°E., 43 lks. dist. mkd. 1/4 S15 BT

A Fir 8" dia., bears S.64 1/2°W., 13 lks. dist. mkd. 1/4 S22 BT

Deposit a white "DEEP-1" magnetic marker at base of stainless steel post.

The corner is located on NE. slope, 100 lks. N. of a gravel road, 25 lks. wide, bears N.65°W. and S.65°E.

Found OK by Max Hull, April 2006 - M150-45