

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 440600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7833)

Set a stone 12x10x4 ins., 8" in the ground, for ¼ sec. cor. marked ¼ on N. face; from which

A Cedar 30" dia., bears N.55¼°E., 85 lks. mkd. ¼ S BT.

A Laurel 3" dia., bears S.57°E., 26½ lks. mkd. ¼ S BT.

Survey by Robert M. Thompson, R.E. #3683 - For: Harbor Plywood Corp. - April 1, 1955 - C.S. File 41/378

Found - A quartz stone, no marks visible.
The BT calls check to a 50" Cedar with face burned out, but old axe work visible, and a clump of Madrone sprouts in place of original Madrone BT.

I renew this corner by marking new BTs in the prescribed manner:

17" D.Fir N.66°15'W., 21.3 ft.

17" D.Fir S.39°50'W., 13.3 ft.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, V. Perron, crew - July 20, 1970 - C.S. File 54/20-53

Found - 17" now 21" Fir, N.66¼°W., 21.3 ft., alive, scribe visible. We tag.

17" now 20" Fir, alive, S.39°50'W., 13.3 ft., blaze healed. We tag.

Orig. Cedar, alive, N.55¼°E., 56.1 ft., axe marks visible.

Set Brass cap at cor. mkd: County Surveyors Office

T 31 S R 4 W

¼ $\frac{S \ 3}{S \ 10}$

1970

This corner lies on steep, SE. slope.

Carl Sweeden - For: Rome Creek Timber - July 2013 - M165-56

Found - 1970 DCSO 2½" brass cap up 0.80'
31" D.Fir BT, N.66°W 21.3', scar vis., tag
Rotted Fir Bt stump, S.40°W., 13.3', rotted, 1.2' tall, replaced tag.

48 cedar BT, N.55¼°E 56.1' (face), scar, 75' tall ±, replaced tag

New BT- 12 D.Fir BT, S.60°E., 29.3', "T31S R4W N ¼ S10 BT" tagged.