

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 451700

PRIMARY CORNER DESCRIPTION Angle point on No. bdy. Sec. 3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 16 Page(s) 6986 ----- Set ¼ sec. post at proper distance; from which A Laurel 6" dia., bears S.6°E., 80 lks. dist. A Chinquapin 4" dia., bears N.45°E., 50 lks. dist.</p>
<p>(NOTE: The above corner by Ford must be in doubt due to statement by Thiel in Vol. 17 Pg. 7024 - "In order to be sure that Deputy Ford did not run the South Bdy. of this Tp. and set any Cors., I went to the Cor. of Tps. 30 and 31 S., R. 5 W., on the offset Meridian Line, - - - -" (V. Laugen, March 1996)</p>
<p>GL0 survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records Vol. 17 Page(s) 7019) ----- Set a Laurel post 3 ft. long, 3" sq., 24" in the ground, for ¼ sec. cor., mkd. ¼ S on N. face, from which A Fir 42" dia., bears S.5°E., 4 lks. dist. mkd. ¼ S BT. A Cedar 12" dia., bears N.27°E., 9 lks. dist. mkd. ¼ S BT.</p>
<p>Wm. Bushey tied and described cor. in GL0 resurvey, under contract #620, dated June 17, 1893 - (DCSO records, Vol. 17 Page 7114)</p>
<p>Survey by John H. Markham, Jr. - Wit: R.G. Boyd - For: Stomar Lumber Co. - Aug. 3, 1960 - C.S. File 42/356-21 ----- Determined from original BTs: 40" Fir S.5°E., 2.6 ft., found scribe on bark and rescribed ¼ S3 BT. 30" Cedar N.27°E., 6.0 ft., I rescribed ¼ S34 BT. At corner point, Set stone, from which 14" Chinquapin bears S.62°W., 33.5 ft. mkd. ¼ S3 R4W BT. 10" Laurel bears S.52°W., 24.5 ft. mkd. ¼ S3 T31S R4W BT. (Note: This is not a ¼ corner to either section, but rather a point on Twp. line since both sections had closing cors.)</p>
<p>Douglas County Surveyors Office - James W. Byron, Deputy - Mike Darby and Milo E. Godfrey, crew - Aug/Sept. 1963 - C.S. File 53/26-103 ----- Found - Both original BTs and both BTs as recorded by Markham. Do not find stone at cor. as recorded byf Markham. Set 3/4" Iron rod at corner.</p>

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 451700

PRIMARY CORNER DESCRIPTION Angle point on No. Bdy. Sec. 3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Gregory Quibell, Deputy - Teresa Buley and John Powell, crew - Dec. 10, 1981 - C.S. File 61/30-1

Found - 3/4" Iron rod, still 2.6 ft. from a 40" Fir. However, this Fir was blown over in a recent windstorm, taking the I.R. over with it.
30" now 27" Cedar with scribed "1/4 S34 BT" in bark.
10" now 12" Madrone, partially uprooted, with rotted face visible in partially healed blaze.
14" now 17" Chinquapin with scribed "1/4 S3 R4W BT" visible.

Using record bearing and distance from 30" now 27" Cedar (S.27°W., 6.0 ft.) I establish a temporary position for corner. From this position, I check bearings and distances to Markham's BTs. Brg. and dist. to 10" now 12" Madrone matches the record (S.52°W., 24.5 ft.) to what I determine to be center of tree before being partially uprooted. Brg. and dist. to the 14" now 17" Chinquapin differ badly from record. BT now bears S.72°W., 37.8 ft. Record is S.62°W., 33.5 ft. Since the temp. position fits two BTs well and also falls in the root hole with good relationship to the approx. center of hole:

I Set a 1" x 30" I.P. with brass cap stamped: "Douglas Co. Surveyor T30S S34 AP S3 R4W T31S 1981" at the location of the temporary position.

New BTs -6" Fir scribed "AP S34 CS BT" in double blaze, bears N.51°E., 12.7 ft.

8" Fir scribed "AP S34 CS BT" in double blaze, bears N.79°E., 39.4 ft.

(Sketch in C.S. File)

Found OK by B. Shaner, July 2000 - M132-37 & CS 65/30-19Q