

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 460600

PRIMARY CORNER DESCRIPTION East 1/16 cor. for Secs. 3 and 10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. -
Wit: R.G. Boyd - March 6, 1959 - C.S. File 42/391-19

At corner point, SET 3/4" x 30" I.P., from which
6" chinquapin bears N.34°W., 11.3 ft. mkd. 1/16 S3 BT.
4" Fir bears S.67°W., 12.7 ft. mkd. 1/16 S3 BT.
Road bears East 160.0 ft.
1/4 Cor. for 3 and 10 bears West, 1303.0 ft.
Sec. cor. for 2, 3, 10 and 11 bears East 1303.0 ft.

Douglas Co. Surveyors office - M. Lenora Ladig; Peter L.
Earle, crew - May 25, 1976 - C.S. File 59/15-8

Found - A 3/4" Iron pipe.
A 6" now 8" Chinquapin bears N.34°W., 11.3 ft. Tree
is alive with partly healed blaze.
A 4" now 8" Fir bears S.67°W., 12.7 ft. Tree alive
with well healed blaze.

At true corner point, Set a 1½" I.Pipe with brass cap mkd:
Douglas Co. Surveyor
T 31 S R 4 W
E 1/16 $\frac{S}{S}$ $\frac{3}{10}$
1976

Placed 3/4" I.Pipe on North side of brass cap.
Corner lies approx. 160 ft. East of Rd. #31-4-3.0